

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instruction
verse side)Form approved.
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.
Las Cruces - 046164, A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
H.W. Andrews9. WELL NO.
210. FIELD AND POOL, OR WILDCAT
Monument11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 11, T-20S, R-36E12. COUNTY OR PARISH 13. STATE
La New MexicoSUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
JAN 24 11 05 AM '672. NAME OF OPERATOR
Amerada Petroleum Corporation3. ADDRESS OF OPERATOR
P.O. Box 668 - Hobbs, New Mexico4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
660' FNL & 660' FFL of Sec. 11

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3583' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☒(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pulled production equipment. Ran Gamma Ray Neutron, Detail, Caliper and Focused logs. Ran tubing with two straddle packers. Swab tested interval from 3802' to 3815'. Recovered water with trace of oil. Swab tested interval from 3820' to 3895'. Recovered water with no oil. Swab tested interval from 3760' to 3797'. Recovered oil and water. Pulled tubing and packers. Spotted 30 sack cement plug from 3801' to 3895' to squeeze off water. Pump tested OH 3760' to 3801'. Acidised OH 3760' to 3801' with 500 gals. NE acid. Reran pumping equipment. Restored well to producing status.

18. I hereby certify that the foregoing is true and correct

SIGNED B. J. LinyTITLE District SuperintendentDATE 1-18-67

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

APPROVED

DATE _____

*See Instructions on Reverse Side

JAN 19 1967
J. I. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

721 H. 2011 11 12