

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NO.	COPIES RECEIVED		
	DISTRIBUTION		
	OFFICE		
	FOR		

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Plug & Abandon		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name Mary J. Byrd
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 2
4. Location of Well UNIT LETTER G , 2310 FEET FROM THE North LINE AND 1650 FEET FROM THE East LINE, SECTION 11 TOWNSHIP 20S RANGE 36E NMPM.		10. Field and Pool, or Wildcat Eunice Monument GSA
15. Elevation (Show whether DF, RT, GR, etc.) 3577' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well was plugged & abandoned in the following manner:

On 2/12/75 rigged up csg pullers & installed BOP. Pulled out of hole w/2-7/8" tbg. Ran cmt retr. Set @ 3700' & cmt'd w/45 sx Cl C cmt w/4% gel & 8#/sk salt. POH w/tbg. Free point indicated 7" csg free @ 440'. Cut 7" csg @ 440' & pulled. Filled hole w/9# gelled mud. WIH w/2-7/8" tbg & spotted 45 sx Cl C cmt cont'g 4% gel & 8#/sk salt 1250-1600' across 9-5/8" csg shoe. Spotted 35 sx Cl C cmt cont'g 4% gel & 8#/sk salt across 7" csg stub 460-314'. Spotted 10 sk cmt plug 40' to surface. Installed regulation dry hole marker & location to be cleaned & levelled.

18. I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNED

TITLE

Dist. Drlg. Supv.

2/21/75

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: