

|                        |  |  |
|------------------------|--|--|
| NO. OF COPIES RECEIVED |  |  |
| DISTRIBUTION           |  |  |
| SANTA FE               |  |  |
| FILE                   |  |  |
| U.S.G.S.               |  |  |
| LAND OFFICE            |  |  |
| OPERATOR               |  |  |

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-71

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|   |  |
|---|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-<br>2. Name of Operator ARCO Oil and Gas Company<br>Division of Atlantic Richfield Company<br>3. Address of Operator<br>P. O. Box 1710, Hobbs, New Mexico 88240<br>4. Location of Well<br>UNIT LETTER C, 330 FEET FROM THE North LINE AND 2310 FEET FROM<br>THE West LINE, SECTION 11 TOWNSHIP 20S RANGE 36E NMPM.<br>15. Elevation (Show whether DF, RT, GR, etc.)<br>3590' GR | 7. Unit Agreement Name<br>8. Farm or Lease Name<br>William P. Byrd<br>9. Well No.<br>1<br>10. Field and Pool, or Wildcat<br>Eunice Monument<br>12. County<br>Lea |
|---|--|

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|   |   |   |   |
|---|---|---|---|
| PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>              | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>             | OTHER <input type="checkbox"/>            | CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/>                |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

- MIRU, POH w/rods & pump. NU BOP. POH w/tbg.
- RIH w/4 1/4" bit, csg scraper & 2-7/8" WS. CO to +3890'. POH.
- Perf Grayburg-San Andres 3848-52' & 3856-62' w/2 JSPF (20 holes) as per PGAC Radiation log dated 8/9/59.
- RIH w/pkr & tbg. Acidize Grayburg San Andres 3848-3874' w/3600 gals 15% HCL-LSTNE acid cont'g 110 gal ARCO S-254 scale inhibitor.
- Swab back load, POH.
- GIH w/compl assy, pump & rods. Return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

|                                  |                                      |                         |
|----------------------------------|--------------------------------------|-------------------------|
| SIGNED <u>Eddie W. Seay</u>      | TITLE <u>Drlg. Engr.</u>             | DATE <u>6/20/84</u>     |
| APPROVED BY <u>Eddie W. Seay</u> | TITLE <u>Oil &amp; Gas Inspector</u> | DATE <u>JUN 23 1984</u> |
| CONDITIONS OF APPROVAL, IF ANY:  |                                      |                         |

RECEIVED

JUN 20 1977

D.C.D.  
HOBBS OFFICE