

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-04225
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name BYRD GAS COM
8. Well No. 5
9. Pool name or Wildcat EUMONT YATES SRQ GAS

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator ARCO PERMIAN	
3. Address of Operator PO BOX 1089 EUNICE NM 88231	
4. Well Location Unit Letter <u>E</u> : <u>1650</u> Feet From The <u>N</u> Line and <u>330</u> Feet From The <u>W</u> Line Section <u>11</u> Township <u>205</u> Range <u>36E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3594-GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. SET CIBP "7" AT 2504' SPOTTED 30 SXS CEMENT FROM 2504' TO 2325'.
2. PULLED TO 2325' DISPLACED HOLE W/9.5# MUD.
3. PERFORATED 7" CSG AT 1287' RIH TO 1287' SPOTTED 40 SXS CEMENT INSIDE & OUTSIDE WOC.
4. RIH TAGGED AT 1198' CALLED OCD WAS ADVISED TO SPOT 10 MORE SXS (SPOTTED 10 SX FROM 1198' TO 1141'.
5. PULLED UP TO 270' SPOTTED CEMENT TO SURF.
6. CUT OFF WELL HEAD INSTALLED DRY HOLE MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE BEN FISHER TITLE FIELD SUPERVISOR DATE 12-20-99
TYPE OR PRINT NAME BEN FISHER TELEPHONE NO. (505) 392-6591

(This space for State Use)

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

GWW

