Submit 3 copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-8

District Office	Revised 1-1-8
O CONSERVATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	30-025-04266
DISTRICT II. Sonto Fo. Now Maxing 97504 2099	5. Indicate Type of Lease
P.O. Box Diawer DD, Artesia, Milit 60210	STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil / Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	The same of the sa
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.	EUNICE MONUMENT SOUTH UNIT B
1. Type of Well: OIL GAS WELL OTHER	
2. Name of Operator	8. Well No. 890
CHEVRON USA INC	050
3. Address of Operator 15 SMITH ROAD, MIDLAND, TX 79705	9. Pool Name or Wildcat GRAYBURG SAN ANDRAES
4. Well Location	STATE OF ATTAINED TO LEG
Unit Letter P: 660 Feet From The SOUTH Line and 660	Feet From The <u>EAST</u> Line
Section 14 Township 20-S Range 36-E NM	IPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3560' GL	
11. Check Appropriate Box to Indicate Nature of Notice, Report,	or Other Data
	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	✓ ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPE	PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEMEN	T JOB
OTHER: OTHER:	UNDER-REAM 🗸
Describe Proposed or Completed Operations (Cleary state all pertinent details, and give pertinent daproposed work) SEE RULE 1103. 7-25-02: MIRU. REL TAC. 7-26-02: TIH W/BIT, SCRAPER TO 3756. SET PKR @ 3615. 7-29-02: RUN TRACER SURVEY ON GRAYBURG COMP 3694-4110. TAG FILL @ 4048. NO FLOW II 7-30-02: TIH W/BIT & TAG FILL @ 4048. BREAK CIRC W/204 BBLS. C/O TO PBTD @ 4110. 7-31-02: TIH W/UNDER REAMER & DC'S TO 3920. UNDER REAM FR 3920-3952. 8-01-02: TAG @ 3952. PU REAMER. TAG @ 3952. BREAK CIRC W/72 BBLS. UNDER REAM FR 3958-02-02: TAG @ 3962. BREAK CIRC W/65 BBLS. UNDER REAM FR 3962-3998. 8-05-02: UNDER REAM 3998-4042. 8-06-02: UNDER REAM 4042-4087. 8-07-02: UNDER REAM 4087-4110. 8-08-02: TIH W/INFLATE PKR. GET ON DEPTH USING GAMMA RAY, ADD 26' SUBS TO GET PKR TEST LINES TO 2250#. ACIDIZE GRAYBURG W/3500 GALS 80/20 MIX OF HCL & SOLVENT (2800 G & EQUIL. TIH W/PKR & SET @ 3680. LOAD HOLE & TEST PKR TO 500#-OK. 8-09-02: RUN TRACER SURVEY ON GRAYBURG COMP 3694-4110. UNSET PKR & LD. 8-10-02: TIH W/TBG PMP OPEN ENDED & 124 JTS TBG & ANCHOR, NDBOP. 8-13-02: SPACE WELL. INSTL POLISH ROD & HANG WELL ON. LOAD TBG, RIG DOWN. CLEAN LOFINAL REPORT	NSIDE OPEN HOLE @ 3965. 52-3962. TO 3887. DROP SV INFLATE PKR. FISH SF. GALS 20% & 700 TOLUENE). UNSET INFLATE
I hereby certify that the pagnished above is true and complete to an expess of my knowledge and belief. SIGNATURE TITLE Regulatory Specialist TYPE OR PRINT, NAME Denise Leake	DATE 10/1/2002

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TIBEIGINAL SIGNED BY GARY W. WINK DATE OCT 1 8 2002