

Memo

3-5-91

From

EVELYN DOWNS
Oil Conservation Staff
Specialist

To whom it may concern —

Per Paul Kautz, the perforations in this well are within the vertical limits of the Eunice Monument South unit B waterflood & no need to be squeezed.