OIL CONSERVATION COMMISSION

HOBBS. NEW MEXICO

April 18, 1957

Morris R. Antweil Box 1058 Hobbs, New Mex.

Gentlemen:

Mr. W. A. Gressett, Oil and Gas Inspector for the Commission, has made an inspection of the location for your Catron No. 1 in Unit L of Section 19, T-20-S, R-36-E and has found that one small pit is not filled, the dead men wires have not been cut and the inscription on the marker reads NW NE 19-20-36 rather than NW SW 19-20-36 as it should.

Please notify this office when the location is ready for a final inspection.

Yours very truly,

OIL CONSERVATION COMMISSION

R. F. Montgomery Proration Manager

mc

OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO

val (01 der ju

ineration of alarma South South Alarma South South

sesonal in the

12. G. S. Spessess, all and the inspector for the Genelastic problem inspection of the location dereission problem is inspection of the location dry year witten to in Unit 1 of Gautian 15, T-20-8, and the une has fone ensity it is not filled, and dest non wires have not been out and the inscription on the marker reads NV HE 19-20-36 rather than HV SW 10-20-36 as it should.

Please notity this affice when the pointion is roody for a final inspection.

Yours very truis,

OL CONSERVATION ANALOSIUM

%. L. Montgumer; Fration Manager

201