

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Federal ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ WELL GAS ☐ WELL OTHER- Injector	7. Unit Agreement Name Eunice Monument South Unit
2. Name of Operator Chevron U.S.A. Inc.	8. Farm or Lease Name
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Well No. 108
4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 25 TOWNSHIP 20S RANGE 36E N.M.P.M.	10. Field and Pool, or Wildcat Eunice Monument G/SA
15. Elevation (Show whether DF, RT, GR, etc.) 3535'	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☒ Dpn, log, perf, adcz, conv to inj.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-22-87 MIRU PU, ND PMP Tee, POH LD rods and prod pmp, blow csg dn, PU Western trt pkr, TIH 60', set pkr, chg out WH, replace w/ 6" 9003000# Gray WH, NU BOP, Test WH to 600# OK. POH, LD 2 3/8 prod tbq, PU bit, FS, DC's, XO, Sub, BHA, 2 7/8" WS, 5-23, PU WS tag at 3829, RU air mist unit, est circ. Wash fill f/ 3829 - 3835. Drlg new form f/ 3835 to 3910, 75'. Circ hole clean, RD swive, PUH to 3700 wait 1 hr. Ck f/Fill, no fill, PUH to 3600, SWIFN, 5-24, TIH, tag at 3910, pmp 60bbls 8.6CKF, POH w/WS and LD BHA, RU dresser atlas, run GR/CNL/CCL w/caliper f/TD to 2900 w/2 repeats, f/TD to 3400, No perfs required. RD WL Co. PU Western TST Pkr, TIH, set at 3695', Load backside, press tst annu at 600# for 30 min. OK. Rise pkr, POH, LD WS, PU 7" baker TSN inj pkr and 120 jts tbq w/pkr at 3678, RU KT, pmp 20bbls pkr fluid set pkr at 3678, ND BOP, fin load annulus w/ 126 bbls pkr fluid. NU tbq bonnett, pkr set w/6000# comp. press to 620#, tst ann. f/30 min. held ok. RD KT RDMOPL Clean location. notified OCD R.A. Sadler and csg int tst on 5-24-87.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY M. E. Chavis TITLE DRLG STAFF ENGINEER DATE JUNE 15, 1987
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR
APPROVED BY _____ TITLE _____ DATE JUN 17 1987
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 16 1937

U.S. DEPT. OF AGRICULTURE
BUREAU OF PLANT INDUSTRY
WASHINGTON, D.C.