

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Charm Oil Company		8. Farm or Lease Name Coll B
3. Address of Operator 801 West Texas, Artesia, New Mexico 88210		9. Well No. 1
4. Location of Well UNIT LETTER N , 1980 FEET FROM THE west LINE AND 660 FEET FROM THE south LINE, SECTION 33 TOWNSHIP 20 S RANGE 36 E NMPM.		10. Field and Pool, or Wildcat Eumont
15. Elevation (Show whether DF, RT, GR, etc.) 3613 RT		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well originally drilled to 3895' w/ 5 1/2" casing cemented with 400 sacks. Should have cemented back to 1200' on top of salt. Propose to load hole w/ mud laden fluid. Place 15 sacks cement across perforations 3830' to 3884'. Knock off 5 1/2" and place 25 sacks cement in and out of stub. Place 10 sacks cement at surface and set regulation marker. Will not disturb 8 5/8" casing.

IN STUB 1/2" casing by 11/11/68
10 sacks cement 11/11/68
25 sacks cement 11/11/68
10 sacks cement 11/11/68

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>Wesley A. Shanon</i>	TITLE Agent	DATE 2-12-68
APPROVED BY <i>Joe R. Hamey</i>	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		