

NEW MEXICO OIL CONSERVATION COMMISSION

COPIES RECEIVED		
DISTRIBUTION		
SALTATE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Other <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-11298

SUNDRY NOTICES AND REPORTS ON WELLS

DON NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Millard Beck	8. Farm or Lease Land State <i>WEG Gas Com</i>
3. Address of Operator P. O. Box 1447, Cimice, New Mexico 88337	9. Well No. 1
4. Location of Well UNIT LETTER <i>H</i> , <i>1790</i> FEET FROM THE <i>North</i> LINE AND <i>660</i> FEET FROM THE <i>East</i> LINE, SECTION <i>34</i> TOWNSHIP <i>20 S</i> RANGE <i>36 E</i> NMPL.	10. Field and Pool, or Both <i>Emmott Y S</i>
15. Elevation (Show whether DF, RT, GR, etc.) 3581' D.F.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING A WELL <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDON WELL <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and rig up pulling unit.
2. Pull tubing and clean out well. Recur tubing.
3. Swab test well.
4. Run sucker rods and subsurface pump if necessary.
5. Rig down pulling unit.
6. Move in and rig up pumping unit, if necessary.
7. Place well back on producing status.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *M. J. Nelson* TITLE *Engineer* DATE *11/18/81*  
APPROVED BY *Orig. Signed L- Les Clements* TITLE *Oil & Gas Inst.* DATE *NOV 18 1981*  
CONDITIONS OF APPROVAL, IF ANY: