

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-1375

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Strata Petroleum Co.	8. Farm or Lease Name Catron-State
3. Address of Operator 503 First Nat'l Bank Bldg., Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER C 607 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 36 TOWNSHIP -20-S RANGE -36-E NMPM.	10. Field and Pool, or Wildcat Summit Yates Seven Rivers
15. Elevation (Show whether DF, RT, GR, etc.) 3599 DF	12. County Lee

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging operations to begin Approx. May 20, 1970

1. Lead hole w/brine water & gel
2. Set 50 sz cement plug on bottom
3. Set 25 sz cement plug in & out of 7" Casing stub
4. Set 25 sz cement plug top of salt section
5. Set 25 sz cement plug in 13 3/8" Casing shoe
6. Set 10 sz cement plug at surface.

TD of well **3860'**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>George Van Hise</u>	TITLE <u>Agent</u>	DATE <u>May 15, 1970</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>MAY 20 1970</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAY 19 1970

**OIL CONSERVATION COMM.
HOBBS, N. M.**