Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

DATE

District Office Revised 1-1-89 DISTRICTI OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 WELL API NO. P.O. Box 2088 30-025-04420 Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATEIX FEE L 1000 Rio Brazos Rd., Azzec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" 7. Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) **EUNICE MONUMENT** Type of Well: GAS WELL WELL X OTHER SOUTH UNIT 2. Name of Operator CHEVRON U.S.A. INC. 8. Well No. 163 3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS 9. Pool name or Wildcat EUNICE MONUMENT/G 14 4. Well Location SOUTH 1980 Unit Letter Feet From The 1980 EAST Line and Feet From The Line **20S** 36 Section Township 36E Range LEA **NMPM** 10. Elevation (Show whether DF, RKB, RT, GR, etc.) County 3549 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING** TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: SOUEEZE, ACDZ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed MIRU, POOH W/PROD. EQUIP. DIG OUT CELLAR AND REPAIR LEAK ON 8 5/8" CASING. SPOT 25 SXS. SAND AT 3886, TAG SAND AT 3757. TST/CSG TO 300 PSI-OK. ACDZ AT3882 W/294 GALS. 15% NEFE, POLOMER SQUEEZE. SWB/ TST ZONE 1 AT 3738-48. SET CIBP AT 3754 SET CICR AT 3640. PUMP 200 SXS. CMT, WOC, DRILL CICR AND TO TOP OF CIBP AT 3754. SWB/TST. DRILL CIBP AND CO TO 3949, PERF 3782-3812 WITH 3 3/8" CSG. GUNS 2 JHF, 180 DEG. PHSD. 61 HOLES. ACDZ 3769-3840 WITH 1000 GALS. 15% NEFE, SWB/TST. RDMO, RETURN TO PRODUCTION. WORK STARTED 8-11-91 WORK ENDED 8028-91. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TECHNICAL ASSISTANT 8-28=91 TYPE OR PRINT NAME P.R. MATTHEWS 687-7812 TELEPHONE NO. (This space for State Use) ないには GRONED ない JERRY SENTLES

APPROVED BY_

DE PROFILEURERVISOR