Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

## OIL CONSERVATION DIVISION

P.O. Box 2088

rict Office	P.O. Box	2088			
	Santa Fe, New	Mexico 87504-2088	0.00	New Wells)	
STRICT I		· ·	API NO. (assigned by OCD of 30-025-04430		
. Box 1980, Hobbs, NM 88240			5. Indicate Type of Lesses		-
STRICT II			5. Indicate Type of ESTATE	☐ FEED	<u> </u>
). Drawer Dd, Artesia, NM 88210			ļ	10	
STRICT III 00 Rio Brazos Rd., Aztec, Nm 87410	,		6. State Oil & Gas Lease		
<b>00</b> 120 0.5			100 100 100 100 100 100 100 100 100 100	Table 4	3: 1 4 2
	REPORT!	S ON WELLS	7. Lesse Name or Unit Ag	reement Name	
	SUNDRY NOTICES AND REPORTS	TO DEEPEN OR PLUG BACK TO A	H. T. ORCUTT (N	CT-C) COM	
OO NOT USE THE	SUNDRY NOTICES AND REPORTS S FORM FOR PROPOSALS TO DRILL OR TO DIFFERENT RESERVOIR. USE "APPLICATION TO PROPOSAL TO PROPOSAL TO PROPOSAL TO PROPOSAL	ION FOR PERMIT"	11		
(50.100)	(FORM C-101) FOR SUCH PROPOSAL	LS.)	┪		
	(FORM C-101) FOR GO				
1. Type of Well:	GAS				
OIL	WELL X OTHER		8. Well No.	5	
WELL			9. Pool name or Wildcat		
2. Name of Operator CHEVRON U.	S.A. INC.		EUMONT		
3. Address of Operator	ND, TX 79702 ATTN: WENDI KIN	NGSTON	660 Feet	From The EAST	Line
P.O. BOX 1150 MIDLA	1D, 1X 79702 /	SOUTH Line are			Count
4. Well Location	D . 000 restriction	Range Range	36E NMI		
Unit Letter 36	Township 10. Eleva	tion(Show whether DF, RKB, RT, GR, etc.)		93.4	
Section	and the second of the second o	3543 GL			
The state of the s	Points Boy to Indecate	Nature of Notice, Report, or Other Da SUBSEQUENT	REPORT OF:		$\Box$
11	Check Appropriate Sex 15		1 1	TER CASING	H
	INTENTION TO:  PLUG AND ABANDON	REMEDIAL WORK	H R	UG AND ABAN.	Ш
PERFORM REMEDIAL WORK	CHANGE PLANS	COMMENCE DRILLING OPNS.	H		IXI
TEMPORARILY ABANDON	Change	CASING TEST AND CMT JOB			لثل
PULL OR ALTER CASING	LI TO ZRVRS	OTHER:			
OTHER: RECOMP F	QUEEN TO 7RVRS	including .		<del></del>	
	pleted Operations(Clearly state all pertinent details, y proposed work) SEE RULE 1103.	, and give pertinent dates, including			
12. Describe Proposed or Comp	y proposed work) SEE RULE 1103.	WILL BOR SET CIBP @3	0 CAR W/10' (	CMT.	
esticated data of state of		SET CIBP @3	300. & CAL MILO	<b></b>	

WORK STARTED 12/05/94: MIRU PU, ND WH, NU BOP. SET CIBP @3300' & CAP W/10' CMT. PERF F/3018'-3088', TOTAL 20 HOLES. ACDZ EACH SET W/150 GALS NEFE ACID. FRAC PERFS W/44,000 GALS 50Q CO2 LINEAR GEL & 160,750 LBS 12/20 BRADY SD. FLUSH. FLOW WELL BACK. ND BOP, NU WH.TURN WELL OVER TO PRODUCTION 12/09/94.

I hereby certify that the information altovally true and complete to the best of my knowledge and belief.  TECH. ASSISTANT	DATE:	12/21/94
SIGNITURE ///	TELEPHONE NO.	(915)687-7826
TYPE OR PRINT NAME WEND! KINGSTON	<b>\</b>	200 to 4
πτιε	DATE	
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:		