P. O. EO. 0+6-MMS-Roswell, 1-File, 1-Engr LM, 1-Foreman EF, I-Laura Richardson, 1-JA Dec. 1973 Budget Bureau No. 42-R1424 UNITED STATES 5. LEASE DEPARTMENT OF THE INTERIOR NM-02053 **GEOLOGICAL SURVEY** 6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) East Eumont Unit 8. FARM OR LEASE NAME 1. oil well other NIO Well well 9. WELL NO. 2. NAME OF OPERATOR 14 10. FIELD OR WILDCAT NAME Getty Oil Company 3. ADDRESS OF OPERATOR Eumont 11. SEC., T., R., M., OR BLK. AND SURVEY OR Box 730, Hobbs, NM 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 AREA below.) Sec. 4, T-19S, R-37E 660' FNL & 660' FEL AT SURFACE: 12. COUNTY OR PARISH 13. STATE AT TOP PROD. INTERVAL: Lea NM AT TOTAL DEPTH: 14. API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) 3701' DF REQUEST FOR APPROVAL TO: SUBSECUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (NOTE: Report results of multiple completion or zone PULL OR ALTER CASING change on Form 9-330.) MULTIPLE COMPLETE CHANGE ZONES ABANDON\* (other) Test Casing 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* 4/4/83 Rig up unit. Ran tbg and pkr, set @ 3600'. Test 4 1/2" csg to 600#, OK. Lay down tbg and pkr. Rig down. T&A Subsurface Safety Valve: Manu. and Type \_\_\_ \_ \_ Set @ \_\_\_\_ Ft. 18. I hereby certify that the foregoing is true and correct

A A MAN

ACCEPTED FOR RECURS Space for Federal or State office use)

APPROVED BY CHESTER TITLE
CONDITIONS OF APPROVAL, IF ANY:

APR 1 1 1983