

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Bonito Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-05568
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-2656

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ TA'd ☐ OTHER Dual Eumont G/SA	7. Lease Name or Unit Agreement Name State A-7
2. Name of Operator Amerada Hess Corporation	8. Well No. 1
3. Address of Operator Drawer D, Monument, New Mexico 88265	9. Pool name or Wildcat Eumont Yates 7 RQ
4. Well Location Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>7</u> Township <u>19S</u> Range <u>37E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3716' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: Cement squeeze Eumont Zone ☒	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to MIRU pulling unit, remove well head & install BOP. TIH & retrieve RBP at 3,400' & TOH. Run pkr. & est. inj. rate into Eumont perms. fr. 3,308' - 3,628'. TIH w/5-1/2" cement retainer set at $\pm$ 3,250' & cement squeeze Eumont Zone perms. fr. 3,308' - 3,628' w/100 sks. class "C" neat cement w/fluid loss additives. WOC. TIH w/4-3/4" bit & drill out retainer & cement to CIPB at 3,790'. Pressure test casing to 500# for 30 min. & resqueeze if necessary. Drill out CIBP to 3,795' & TOH. TIH w/mill, mill over pkr. & recover pkr. TIH w/bit & run bit to PBD at 3,990' & TOH. TIH w/tbg., remove BOP & install well head. RDPU & clean location.

Close well in for water flood operations in G/SA Zone.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. L. Wheeler, Jr. TITLE Supv. Adm. Svc. DATE 12/13/91
TYPE OR PRINT NAME R. L. Wheeler, Jr. TELEPHONE NO. 393-2144

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: