## NEW MEXICO OIL CONSERVATION COMMISSION

Form C-128

Well Location and/or Gas Progration Plat

			12-5-56					
Operator Tidewater Oil Co.				Lease State AI				
	no est nacionale de maria e al mariamento approvamento en este maria.	The same of the second section of the sectio	The Control of the Co	CEO T	7	10 i 05		
Well No	2	Section	<u>15</u> Town	ship <u>19</u>	South	Range 37	East NMPM	
Located_	660	Feet From	West	Line	1980	Feet From_	North Line,	
	Lea		Sounty, New M	iaxudo.	G L.	Elevation		
Name of	Producing	Formation	Queen	Posi	Eumont	Dedicated	Acreage 40	
	(N)	ote: All distanc	res must be fr	om auter	bounda	ries of Section	,)	
	-		A STATE OF THE STA	<b>5</b> % "性不 <b>能</b> 不少是4757"的数据中心 <b>是</b> 数	C. P. at 2 A STORE THE PARTY.	The of occitor	-, <b>1</b>	
					1			
					1			
					1			
		930			!			
		-			j.			
	2+.	WORKS BEECH BETTER STEELS STEELS STEELS		e estate des significación es	+	- <del></del>	4	
					1			
	-6	601			į. Ł			
					1			
					1			
		•			į			
	The state of the s	market process - program regional and security should be supplied to the security of the secur	The term of the second of the	e nem seen of a constitution			4	
	-	Ì						
		!						
		1			i			
		1			1			
		· 						
		-		e eren ere in me			1	
		ļ 1						
		1			1			
					1			
					.			
l. Is this	Well a D	ale:r=kao' ual Comp. ? Ye.	e NJ.	Marketter of the state of the s				
		adi wwiip Te	2 140	1 lils mrana	is to ce. Ded from	rtify that the a	bove plat was	
2. If the answer to Question 1 is yes, are there any other dually completed wells within the					prepared from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the			
dedicat	ed acreag	ge? YesN	0			nowledge and b		
Vaine				<b>5</b> 3	سر			
O sition				Date	Date Surveyed 12-5-56			
Representing				Revis	Registered Professional Engineer			
Address				Registered Professional Engineer and/or Land Surveyor				