

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B1382-1	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation		8. Farm or Lease Name State "G"
3. Address of Operator Drawer D, Monument, New Mexico 88265		9. Well No. 2
4. Location of Well UNIT LETTER <u>L</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>18</u> TOWNSHIP <u>19S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat Eunice Monument G/SA
15. Elevation (Show whether DF, RT, GR, etc.) 3714' DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-17-87 to 5-20-87

MIRU pulling unit & pulled rods, pump & tbg. Perforated Grayburg San Andres Zone open hole at the following intervals: 3954' - 3965', 3970' - 3980', & 3998' - 4010' w/2 90 gram jet shots per foot. Ran pkr. & tbg. & set pkr. at 3877'. Acidized Grayburg San Andres zone in open hole fr. 3946' to 4045' w/2500 gal. 15% NEFE HCL acid in stages. Flushed w/30 bbls. 2% KCL water. Swabbed, pulled tbg. & pkr. & re-ran tbg., pump & rods & resumed pumping.

6-1-87: Pumped 20 b.o., 20 b.w., & 70 MCFGPD on 8.5 x 54" SPM in 24 hrs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. L. Whelan Jr. TITLE Supv. Adm. Svc. DATE 6-8-87

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE JUN 11 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUN 10 1987
OCD
HOBBS OFFICE