

Lease #416
606

(SUBMIT IN TRIPLICATE)

Lease C


Budget Bureau 42-R358.3.
Approval expires 12-31-55.

No 034075

Field Office

Lease No.

Unit

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sundary-State "X" Gas Well

Fort Worth, Texas, March 13, 1956.

Well No. 1 is located 760 ft. from [S] line and 1980 ft. from [E] line of sec. 18

SW 1/4 of Sec. 18 19-4 37-E NHPN

Ransom Gas (Field) Lea (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 3700 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

FORMATIONS REPORTED	SIZE CASING	CASING PROGRAM (Approx.)
Top of Anhydrite 1285'	8-1/8" 24# New	1350'
Top of Yates 2585'	4-1/2" 11.60# New	3450'
Top of Queen 3945'		
Top of Pennrose 3450'		
Total Depth 3600'		

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company THE TEXAS COMPANY

Address P.O. Box 1780
Fort Worth, Texas

THE TEXAS COMPANY

By J. J. Veltan

Title Division Civil Engineer

[Faint, illegible text covering the upper two-thirds of the page, possibly bleed-through from the reverse side.]

173

[Faint, illegible text at the bottom of the page, possibly bleed-through from the reverse side.]