NO. OF COPIES RECEIVED	-		Form C-103 Supersedes Old
ANTAFE	NEW MEXICO	C-102 and C-103 Effective 1-1-65	
FILE			Ellective 1-1-02
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State Fee
OPERATOR			5. State Oil & Gas Lease No.
SUNE	PRY NOTICES AND REPO	ORTS ON WELLS	3-1305
(DO NOT USE THIS FORM FOR FUSE "APPLIC	PROPOSALS TO DRILL UT AT DEEPEN ATION FOR PERMIT - 1 (500M C-10	RTS ON WELLS FOR PLUG BACK TO A DIFFERENT RESERVOIR.	
OIL GAS WELL	OTHER-		7. Unit Agreement Name
2. Name of Operator TEXACO Inc.			8. Form or Lease Name New Mexico K State
P. O. Box 72°,	Hobbs, New Mexic	o 88 24 0	9. Well No.
4. Location of Well	-1960+// <	Rorth 650	EUT EGO-MOULING HO
UNIT LETTER	FEET FROM THE	LINE AND FEET F	arayburg San Andres
THELINE, SEC			PM. (
		w.whether DF, RT, GR, etc.)	12. County
Check	Appropriate Box To Ind	licate Nature of Notice, Report or	
NOTICE OF	INTENTION TO:		INT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABAN	NDON REMEDIAL WORK	ALMERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
OTHER			
2. Ran Lyne oper No communicate gals. injects Pulled out of 3+27-75. Kill 3. Fulled rods a 3918, 3925, 3 4. Acidize OH 32 1600/. 5. On 24 hr test water. Grav	hole ret on 2 ition around ret. Followed by the ret and neverse led well w/140 by and tubing. Perf 3927. Set par at 148-3934 w/500 grant at 2:00 p.s.	Howco pumpediinto some 50 sx class "C" cmt. Man 50 sx class "C" cmt. Man 60 cmt. Man 2-7/8" to 5-1/4" OH w/2 JSPI st 3776". al SAP Mark II, 1,000 gran. 4-29-75, well pumped Prod from Orevours San	x press 4000, Min 100, TD. Comp 8:00 p.m. ubing and rods. 3662, 3698, 3902, 3907
3. I hereby certify that the information	above is true and complete to t	the best of my knowledge and belief.	at B.un me
GNED JACK	тіт		Pt. 4-30-75
7	C+ on one		[e ^y]

conditions of approval, if any: $D(st.\ I,\ Super.)$