IRGY AND MINERALS DE				
CONSERVATION DIVISION  P. O. BOX 2088				•
				Form C-103 -
SANTA FE, NEW MEXICO 87501				Revised 10-1-7
PILE			3,1,00 0,301	
U.S.G.1.			•	Sa. Indicate Type of Lease
LAND OFFICE	1-1-1			State Foo X
OPERATOR				5. State O'l & Gas Lease No.
	6111001111071071			
SUNDRY NOTICES AND REPORTS ON WELLS  THE PORM FOR PROPOSALS TO DRILL OR TO OCCUPEN OF PLUC BACK TO A DIFFERENT RESCRIVOIR.  USE "APPLICATION FOR PERMIT -" FORM C-1011 FOR SUCH PROPOSALS.)				
SIL CAS	OTHER-			7. Unit Agreement Name
Chevron U.S.A. Inc.				8. Fam or Lease Name B.V. Culp (NCT-A)
dreas at Operator				9. Weil No.
P.O. Box 570 Hobbs, NM 88240				1
Cattou of Mell	660	North	1980	10. Field and Pool, or Wildcat
UNIT LETTER		1401 L	INC AND FEET P	Eunice Monument GR-84
West	19	198	37E .	
· · · · · · · · · · · · · · · · · · ·	NC, SECTION	_ TOWNSHIP	RANGE WM	···· (
15. Elevation (Show whether DF, RT, GR, etc.)				12, County
	////////		•	Lea
	Check Appropriate Bo	ox To Indicate Natur	re of Notice, Report or	Other Data
NOTIC	E OF INTENTION TO:			ENT REPORT OF:
ORM REMEDIAL WORK	PI	RES ON ABANDON	MEDIAL WORK	ALTERING CASING
PORARILY ASAHOON		cox	MENCE DRILLING OPHS.	PLUG AND ABANDONMENT
OR ALTER CASING	c.	MANGE PLANS CAS	SING TEST AND CEMENT JOB	
Shut off w	ater influx		OTHER	
THER SINC OFF W	a cer illitux			
. Proposed or Con	nieted Operations (Clearly	state all positions desails		
ork) SEE RULE 1103.		state all pertinent details, i	and give pertinent dates, includ	ing estimated date of starting any proposed
Find and i	solate water influ	ux. Repair as ne	cessary. Return to	production.
			,	_
		•		÷
	•	•		
			•	
•		•		
		•		
		•		
	•			•
		•		
	•			
			•	

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

TITLE

TITLE

Drilling Superintendent

DISTRICT I SUPERVISOR

TITLE

TITLE

Drilling Superintendent

DISTRICT I SUPERVISOR

TITLE

OATE

OATE