OIL WELL DRILLING COMPANY

NO STOCKHOLDERS LIABILITY

 \sim

1123 ATHLETIC CLUB BUILDING

DALLAS, TEXAS

Hobbs, New Mexico September 11, 1936

Mr. P. J. Vesley State Oil & Gas Inspector Carlsbad, New Mexico

Dear Sir:

Supplementing our completion report on our P. C. Klingsmith well No. 1, in SET SET Section 20, T 19S, R 37E, Monument field.

Wish to advise that prior to running 3880° of 27/8" OD tubing, a previous string was dropped in the hole and was recovered with the exception of four joints plus approximately 26° of another joint. After fishing for several days and discussing the condition with Mr. C. G. Staley, the above amount of tubing was left in the hole.

Yours very truly

HTC:B