NEW MEXICO OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO

MISCELLANECIUS NOTICES

SUBMIT THIS NOTICE IN TRIPLICATE TO THE DISTRICT OFFICE, OIL CONSERVATION COMMISSION, BEFORE THE WORK SPECIFIED IS TO BEGIN. A COPY WILL BE RETURNED TO THE SENDER ON WHICH WILL BE GIVEN THE APPROVAL, WITH ANY MODIFICATIONS CONSIDERED ADVISABLE, OR THE REJECTION BY THE COMMISSION OR AGENT, OF THE PLAN SUBMITTED. THE PLAN AS APPROVED SHOULD BE FOLLOWED, AND WORK SHOULD NOT BEGIN UNTIL APPROVAL IS OBTAINED. SEE ADDITIONAL INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION.

INDICATE NATURE OF NOTICE BY CHECKING BELOW

NOTICE OF INTENTION						
TO CHANGE PLANS	NOTICE OF TEMPORARII	INTENTION TO Y ABANDON WELL	NO 10	TICE OF INTENTION DRILL DEEPER		
NOTICE OF INTENTION TO PLUG WELL	X NOTICE OF TO PLUG BA	INTENTION ACK	NO TO	TICE OF INTENTION SET LINER		
NOTICE OF INTENTION TO SQUEEZE	NOTICE OF TO ACIDIZE	INTENTION	NO TO	TICE OF INTENTION SHOOT (NITRO)		
NOTICE OF INTENTION TO GUN PERFORATE	NOTICE OF (OTHER)	INTENTION	NO	TICE OF INTENTION		
OII. CONSERVATION COMMISSANTA FE, NEW MEXICO	SION	Hobbs, New Mex	ico	August	13, 19	57
	-	(PLACE)			DATE	/ t
GENTLEMEN:				•		
FOLLOWING IS A NOTICE	F OF INTENTION TO	BO 6235 10111				
FOLLOWING IS A NOTICE	- Nove Manual	DO CERTAIN WO	rk as describ	ED BELOW AT T		
Humble Oil & Refining Con	COMPANY OR OPERATOR	co State AT	WELL N	0_2	IN	
NE W SW WOF	EC. 26 T	195 月 37世	NAC DAA	turiont		(UNIT)
(40-ACRE SUBDIVISION) Lea	COUNTY.		I diate lafe'	040110110		POOI
To plug and abandon well	as follows:	ONS IN THE RULES	AND REGULA	ITIONS)		
L. Place cement plug in 2. Cut and pull 52" csg 3. Set 200' cement plug 4. Remove wellhead and p Place marker over wel Interval open to prod Casing Program: 8-5/8	t as follows: 5½" csg from agat approximatel from 400 to 600 lace 20' plug i	proximately 39 y 500'. n top of 8-5/8 y NMOCC.	550 to 3704 3" casing.	(P3D).		
L. Place cement plug in 2. Cut and pull 52" csg 3. Set 200' cement plug 4. Remove wellhead and p Place marker over wel Interval open to prod Casing Program: 8-5/8	t as follows: 5½" csg from apat approximatel from 400 to 600 lace 20' plug i 1 as required b uction: Perfor	proximately 39 y 500'. n top of 8-5/8 y NMOCC.	om 3626 to nted to surto 550'.	(P3D).	mpany	
L. Place cement plug in 2. Cut and pull 5½" csg 3. Set 200' cement plug in Remove wellhead and pull place marker over well Interval open to rod Casing Program: 8-5/8 5½" c	as follows: 5½" csg from ap at approximatel from 400 to 600 lace 20' plug i l as required b uction: Perfor " csg set at 31 sg set at 3950'	proximately 3: y 500'. n top of 8-5/8 y NMOCC. ated casin, fr 3.48' and ceme and cemented	casing. casing. com 3626 to nted to sure to 550'. Humble Oil	(PBD). 3658:		
L. Place cement plug in 2. Cut and pull 5½" csg 3. Set 200' cement plug in Place marker over wel Interval open to rod Casing Program: 8-5/8 5½" c	as follows: 5½" csg from ap at approximatel from 400 to 600 lace 20' plug i l as required b uction: Perfor " csg set at 31 sg set at 3950'	proximately 3: y 500'. n top of 8-5/8 y NMOCC. ated casin, fr 3.48' and ceme and cemented	casing. casing. com 3626 to nted to sure to 550'. Humble Oil	(PBD). 3658*. Cace.		
L. Place cement plug in 2. Cut and pull 5½" csg 3. Set 200' cement plug in Remove wellhead and pull place marker over well Interval open to rod Casing Program: 8-5/8 5½" c	as follows: 5½" csg from ap at approximatel from 400 to 600 lace 20' plug i l as required b uction: Perfor " csg set at 31 sg set at 3950'	proximately 3: y 500'. n top of 8-5/8 y NMOCC. ated casing fr 3.48' and ceme and cemented BY POSITION	casing. casing. com 3626 to nted to sure to 550'. Humble Oil Comp. Agent SEND COMMUNICATION	(PBD). 3658:. Face. & Refining Co	WEU TO:	
L. Place cement plug in 2. Cut and pull 52" csg 3. Set 200' cement plug in lemove wellhead and pull place marker over wel Interval open to rod Casing Program: 8-5/8 52" c APPROVED EXCEPT AS FOLLOWS:	as follows: 5½" csg from ap at approximatel from 400 to 600 lace 20' plug i l as required b uction: Perfor " csg set at 31 sg set at 3950'	proximately 3: y 500'. n top of 8-5/8 y NMOCC. ated casin, fr 3.48' and ceme and cemented	casing. casing. com 3626 to nted to sure to 550'. Humble Oil Comp. Agent SEND COMMUNICATION	(PBD). 3658:	WEU TO:	