

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-05714

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B246-1

7. Lease Name or Unit Agreement Name

NORTH MONUMENT G/SA UNIT
BLK. 12 #04

8. Well No.

NMOCD No. 288

9. Pool name or Wildcat

EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Amerada Hess Corporation

3. Address of Operator

P.O. DRAWER D, MONUMENT, NM 88265

4. Well Location

Unit Letter D : 660 Feet From The NORTH Line and 660 Feet From The WEST Line

Section 28 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: RE-ACTIVATE WELLBORE. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1204 (09-13-96 THRU 10-18-96)

TYLER WELL SVC. MIRU. RMV'D. THE P&A MARKER & INSTALLED THE BOP. STAR TOOL RAN A BIT ON 1 D.C. TAGGED UP AT 6' FR. SURF. BROKE CIRC. & DRLD. CMT. TO 97'. CIRC. CLEAN. RAN THE BIT TO 216' & TAGGED UP. DRLD. CMT. TO 221'. RAN TO 2,165' & TAGGED UP ON CMT. RETAINER W/ 6 D.C.'S & 64 JTS. OF 2-7/8" TBG. CIRC. CLEAN. TAGGED UP AT 2,165' W/6 D.C.'S & 64 JTS. OF 2-7/8" TBG. DRLD. SOFT CMT. TO 2,261' & HARD CMT. TO 2,283'. DRLD. OUT THE CMT. RETAINER @ 2,383' & HARD CMT. TO 2,378'. RAN THE BIT TO 2,440' & CIRC. CLEAN. RAN BIT TO 3,280' & CIRC. OUT HEAVY MUD TO 3,375'. CIRC. CLEAN. CLEANED OUT HEAVY MUD FR. 3,375' TO 3,565' & CMT. FR. 3,565' TO 3,596'. TAGGED UP ON THE CIBP @ 3,596'. CIRC. CLEAN. PRESS'D. UP ON THE CSG. STRING TO 520#. LOST 200# IN 30 SECS. STARTED OUT OF THE HOLE W/TBG., D.C.'S & BIT GOT (CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE SR. STAFF ASSISTANT

DATE 10-31-96

TYPE OR PRINT NAME TERRY L. HARVEY

TELEPHONE NO. 505-393-2144

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

JAN 14 1997

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: