

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 300250574400
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1533 1/2
7. Lease Name or Unit Agreement Name State "AC" <i>Chm</i>
8. Well No. 2
9. Pool name or Wildcat Eunice Monument Grayburg/San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Conoco Inc.	3. Address of Operator 10 Desta Dr. Ste 100W, Midland, TX 79705-4500	4. Well Location Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line Section 30 Township 19S Range 37E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3672 GR
--	------------------------------------	---	---

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: Perforate Additional Pay <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to perforate and acidize the Grayburg formation in the State "AC" No. 2 well using the following measures:

1. RIH with 4" HSC perforating gun and perforate from 3858'-3850', 3846'-3840', 3838'-3834', 3831'-3824', 3818'-3806', 3796'-3792', 3782'-3768' with 2 JSPF.
2. Set RBP @ 3875'.
3. Acidize with 5000 gallons of 15% HCl.
4. Swab back acid load and POOH with RBP.
5. Place well on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Jerry W. Hoover* TITLE Sr. Conservation Coordinator DATE Sept. 18, 1991

TYPE OR PRINT NAME Jerry W. Hoover

TELEPHONE NO. (915) 686-654

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: