

**OIL CONSERVATION DIVISION**

**DISTRICT I**  
P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-05754

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
B-5553

7. Lease Name or Unit Agreement Name  
NORTH MONUMENT G/SA UNIT  
BLK. 10

8. Well No.  
9

9. Pool name or Wildcat  
EUNICE MONUMENT G/SA

| SUNDRY NOTICES AND REPORTS ON WELLS<br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)         |  |
|--|--|
| 1. Type of Well:<br>OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION  |  |
| 2. Name of Operator<br>Amerada Hess Corporation  |  |
| 3. Address of Operator<br>P.O. DRAWER D, MONUMENT, NM 88265  |  |
| 4. Well Location<br>Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line<br>Section <u>30</u> Township <u>19S</u> Range <u>37E</u> NMPM LEA County |  |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.)   |  |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: CONVERT TO INJECTION WELL ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1009 (08-22-1996 THRU 09-03-96)

PRIDE WELL SVC. & STAR TOOL MIRU. UNSEATED PUMP & TOH W/PROD. EQUIP. ND WELLHEAD, RELEASED TAC. & INSTALLED BOP. TOH W/TBG. SUB, TBG., TAC, SALTA & SN. TIH W/RBP, SN & TBG. SET & GOT OFF RBP @ 3,740'. BROKE CIRC. & CIRC. CLEAN. PRESS. TST'D. CSG. TO 580# & CHARTED 30 MIN. TST. CSG. HELD. BROKE OUT INT. RISER & FOUND CMT. TO SURF. IN CSG. HEAD. TOH W/TBG., SN, & RETRIEVING HEAD. LOADED 7" CSG. W/WATER & POURED 3 SKS. SAND DWN. CSG. TO COVER RBP @ 3,740'. BACKHOE DUG OUT CELLAR BELOW INT. CSG. HEAD. HIT SOLID CONCRETE IN BTM. OF CELLAR. UNABLE TO LOCATE 13" SURF. CSG. DUE TO CONCRETE. ND BOP, BROKE OUT RISER ON CSG. HEAD & CHK'D. OUTLETS W/EXPLOSION METER. SAFE. INSTALLED NEW WELLHAD TO 2,500#. INSTALLED BOP. TIH W/RETRIEVING HEAD, SN, & TBG. TAGGED SAND @ 3,725'. CIRC. SAND OFF FR. 3,725'-3,740' & RELEASED RBP.  
(CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 09-04-96  
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

SEP 17 1996

JC BA

dp