

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05755
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-5553
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 10
8. Well No.	15
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. DRAWER D, MONUMENT, NM 88265	
4. Well Location Unit Letter 0 : 330 Feet From The SOUTH Line and 2310 Feet From The EAST Line Section 30 Township T19S Range R37E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: CONVERT TO INJECTION WELL. ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1015

MIRU PULLING UNIT & REVERSE UNIT. ND WELLHEAD. TOH & LAY DWN. RODS & PUMP. DN WELLHEAD. NU BOP. TOH W/TBG. TIH W/RBP & SET @ +/-500'. INSTALL NEW WELLHEAD EQUIPMENT. TIH W/TBG. & RETRIEVE RBP. TOH W/RBP. TIH W/BIT, D.C.'S & TBG. CLEAN OUT TO TD @ 3,935'. TOH W/BIT. RU WIRELINE CO. & STRING SHOOT OPENHOLE W/400 GR/FT TO REMOVE BARIUM SCALE. RD WIRELINE. RU SCHLUMBERGER & LOG THE OPENHOLE W/SONIC/CNL/GR TOOLS. RU CEMENTERS. TIH W/TBG. OPENENDED & SPOT CEMENT PLUG FR. 3,935' TO 3,900'. (USE OYSTER SHELLS TO ESTABLISH CIRC. IF NECESSARY). WOC 24 HOURS. TIH W/4" CSG. GUN. PERFORATE. (INTERVAL TO BE DETERMINED FR. LOGS). RD SCHLUMBERGER. TIH W/A SONIC HAMMER ON TBG. TO TD. RU ACID CO. ACIDIZE WELL W/4,000 GALS. 15% NEFE DI HCL W/3% DP-77MX MICELLAR SOLVENT. TOH W/SONIC HAMMER. TIH W/TBG. & PKR. SET (CONTINUED ON PAGE 2)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 02-21-96
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____

FEB 26 1996