

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-05770
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTH MONUMENT G/SA UNIT BLK 15
8. Well No. 11
9. Pool name or Wildcat EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> INJECTION	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. BOX 840 SEMINOLE, TX 79360	
4. Well Location Unit Letter <u>K</u> : <u>2310</u> Feet From The <u>SOUTH</u> Line and <u>2310</u> Feet From The <u>WEST</u> Line Section <u>31</u> Township <u>19S</u> Range <u>37E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>CONVERT TO INJECTION WELL</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/20/1998 THRU 1/29/1998 ORDER NO. R-9596 ADMIN ORDER NO. WFX-716

MIRU DAWSON WELL SVC. & TOH W/RODS & PUMP. REMOVED WELLHEAD, INSTALLED BOP & TOH W/TBG. TIH W/4-1/2" MD. G RBP SET AT 3810'. REMOVED BOP. REMOVED OLD WELLHEAD & INSTALLED NEW WELLHEAD. RE-INSTALLED BOP. TIH W/RETRIEVING HEAD, LATCHED ONTO & TOH W/RBP. TIH W/BIT TAGGED AT 3865' & CLEANED OUT TO 3885'. CIRC. CLEAN. WESTERN ATLAS RAN GRN/CCL LOGS. TIH & PERF. 4-1/2" LINER USING 2-1/8" ENERJET CHARGES W/2 SPF, TOTAL 207 SHOTS FR. 3726' - 3754', 3762' - 3774' & FR. 3782' - 3844'. AMERICAN FRACMASTER ACIDIZED PERFS. & O.H. W/5400 GAL. 15% HCL ACID. SWABBED WELL. TIH W/4-1/2" ARROWSET IXS PKR. ON 2-3/8" POLYLINE TBG. & SET PKR. AT 3703' W/8000# TENSION. CIRC. PKR. FLUID. PRESS. TESTED CSG. TO 540 PSI FOR 30 MIN. HELD OK. CHART ATTACHED. RDPU & CLEANED LOCATION. CONTINUED OVER

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Colleen Robinson TITLE Staff Assistant DATE 2-5-1998
TYPE OR PRINT NAME Colleen Robinson TELEPHONE NO. 915-758-6738

(This space for State Use)

ORIGINAL SIGNED BY
GARY WINK
FIELD REP. II

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ICJSN

FEB 26 1998

dp