

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**DISTRICT I**  
P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05775
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
North Monument G/SA Unit Blk. 15	
8. Well No.	6
9. Pool name or Wildcat	Eunice Monument G/SA

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P. O. Box 840, Seminole, Texas 79360-0840	
4. Well Location Unit Letter <u>F</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>2310</u> Feet From The <u>West</u> Line Section <u>31</u> Township <u>19S</u> Range <u>37E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11.

**Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-19 thru 4-3-97

MIRU Tyler Well Svc. & Star Tool. TOH w/rods & pump. Removed wellhead, installed BOP & TOH w/tbg. TIH w/6-1/8" bit, cleaned out fill fr. 3909' - 3930' & TOH. Schlumberger ran CNL/GR/CCL fr. 3930' - 3200'. Perforated Grayburg San Andres Zone 7" csg. using 4" hegs csg. gun w/2 SPF, total 113 shots, fr. 3744' - 3800'. TIH w/RBP set at 1682' & press. tested 7" csg. to 540#. Held OK. Poured 3 sks. sand down csg. to cover RBP. Installed new wellhead. TIH, circ. sand off RBP, latched onto RBP & TOH. Knox Svc. acidized G/SA Zone csg. perms. fr. 3744' - 3800' & O.H. fr. 3811' - 3930' w/5800 gal. 15% NEFE HCL acid. Swabbed well. TIH w/7" x 2-7/8" Baker TAC on 2-7/8" tbg. & set tbg. at 3909' w/TAC at 3721'. Removed BOP & installed wellhead. TIH w/pump & rods. RDPU, cleaned location & resumed pumping well.

Test of 4-6-97: Produced 14 b.o., 17 b.w., & 37 MCFGPD in 24 hours.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. L. Wheeler, Jr. TITLE Admin. Svc. Coord. DATE 4-7-97

TYPE OR PRINT NAME R. L. Wheeler, Jr. TELEPHONE NO. 915 758-6778

(This space for State Use)

ORIGINAL SIGNATURE BY STATE EXEMPT

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

APR 11 1997