

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-		7. Unit Agreement Name
2. Name of Operator <u>Atlantic Richfield Company</u>		8. Farm or Lease Name <u>J. R. Phillips "B"</u>
3. Address of Operator <u>Box 1710, Hobbs, New Mexico 88240</u>		9. Well No. <u>3</u>
4. Location of Well UNIT LETTER <u>F</u> <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>31</u> TOWNSHIP <u>19S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat <u>Eunice Monument</u> <u>Grayburg SA</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3585' GL</u>		12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER <u>Cmt Squeeze Oil Flow on 10-3/4"</u> ☒
		Intermediate Csg, Acidize & return to prod.	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RU 1/10/79. POH w/compl assy, inst BOP. RIH w/pkr & RBP, set BP @ 3607'. Tested 7" csg 0-3607' w/1000# OK. Ran CBL-GR-CL, TOC @ 2500'. Perforated 7" csg w/4 holes 2410-2412'. RIH w/cmt retr, set retr @ 2340'. Squeezed holes 2410-2412' w/250 sx C1 C w/2% CaCl. Perforated squeeze holes 1760-1762'. RIH w/cmt retr, set retr @ 1716'. Squeezed holes 1760-1762' w/650 sx Howco lite cmt followed by 250 sx C1 C Neat followed by 250 sx C1 C w/2% CaCl. Circ 30 sx cmt to surf thru intermediate, closed intermediate & squeezed 100 sx into fm. RO 5 sx cmt. WOC 47 hrs. Drld cmt & cmt retr @ 1716'. Press tested 7" csg to 1000# 30 mins OK. Drld cmt retr @ 2340' & cmt to 2412'. Pressure tested 7" csg to 1000# 30 mins OK. Rev sd off top of BP @ 3607'. POH w/BP. RIH w/pkr, set pkr @ 3540'. Acidized OH 3811-3930' w/1000 gals 15% NE acid. RIH w/compl assy and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] for LD Lane TITLE Dist. Drlg. Supt. DATE 3/23/79

Orig. Signed by

Jerry Sexton

TITLE Dist. L. Supv.

DATE APR 2 1979

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY: