

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30-025-05780
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	N/A
7. Lease Name or Unit Agreement Name	J.R. PHILLIPS 'A'
8. Well No.	8
9. Pool name or Wildcat	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P & A ' D	
2. Name of Operator Amerada Hess Corporation = <i>Atlantic Richfield Co</i>	
3. Address of Operator P. O. Box 840, Seminole, Texas 79360-0840	
4. Well Location Unit Letter <u>M</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>942</u> Feet From The <u>WEST</u> Line Section <u>31</u> Township <u>19S</u> Range <u>37E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3572' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <u>RE - P&A FOR WATERFLOOD COMPLIANCE</u> <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify NMOCD 24 hours prior to rigging up on well.

1. Drill out plug from 0-30' and tag plug at 5742'.
2. Circulate hole w/ 135 barrels 10# brine w/ 25# gel per barrel.
3. Spot 25 sx Cl 'H' cement from 5100-4897' (base of unitized interval).
4. Spot 25 sx Cl 'H' cement from 3645-3442' (top of unitized interval).
5. Spot 25 sx Cl 'H' cement from 2300-2097' (base of salt section).
6. Spot 25 sx Cl 'H' cement from 1083-880' (top of salt section).
7. Spot 10 sx Cl 'H' cement from 81-0'.
8. Cap and mark with 4" pipe extending 4' above ground.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE CHGS TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Chad McGehee TITLE Petroleum Engineer DATE 04-23-98

TYPE OR PRINT NAME Chad McGehee TELEPHONE NO. 915 758-6707

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY TITLE DATE
CONDITIONS OF APPROVAL, IF ANY:

APR 28 1998

Amerada Hess is the operator of the NMGSAU Waterflood.
This well was originally P&A'd by Sinclair/Arco in 1971.

