100

NEW LEXICO OIL CONSERVATION CO. ISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

of the Commission. Indicate nature of	of report by checking below	v:	
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RE	PAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	REPORT ON PUI	LING OR OTHERWI	SE .
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	X REPORT ON DER		
REPORT ON RESULT OF PLUGGING OF WELL			
Monument, New		D ecember	23. 1936
OIL CONSERVATION COMMISSION,	Place		Date
Santa Fe, New Mexico. Gentlemen:			
	-		
Following is a report on the work done and the resu	ilts obtained under the hear	ding noted above at	the
Amerada Petroleum Corporation Company or Operator	Larsen	Well No	in t
SW4 NW4 of Sec. 32	Lease 19	3 7	
Monument Field,	, 1	_, R	, N. M. P. N
The dates of this work were as follows:			Count
Notice of intention to do the work was [was not] sub	hmitted To C-100	D 1 00	
and approval of the proposed plan was [was not] obtained	- Torm C-102 on	DECHARDEL CO.	19
DETAILED ACCOUNT OF Wester 122 40 4 8-Thd. New Eapweld casing was the Halliburton Method with 200 sacks.	ORK DONE AND RES	ULTS OBTAINE	
12½" 40# 8-Thd. New Eapweld casing was the Halliburton Method with 200 sacka. Coment was drilled out of the casing actand undistubbed for one hour. The best fany water had accumulated. No water esumed.	ORK DONE AND RES	ults obtained at 200 and cented dry and at 1	onted by
122" 40# 8-Thd. New Eapweld casing was the Halliburton Method with 200 sackd. Cement was drilled out of the casing are stand undistubbed for one hour. The best fany water had accumulated. No water resumed. Witnessed by Ita French	ORK DONE AND RES	ults obtained at 200 and cented dry and at 1	owed to to determines then
12½" 40# 8-Thd. New Eapweld casing was the Halliburton Method with 200 sacka. Cement was drilled out of the casing a stand undistubbed for one hour. The beif any water had accumulated. No water resumed.	ORK DONE AND RES	ut 200° and cented dry and all o bottom again the drilling	onted by owed to to determinates was then
12½" 40# 8-Thd. New Eapweld casing was the Halliburton Method with 200 sacka. Cement was drilled out of the casing ar stand undistubbed for one hour. The being any water had accumulated. No water resumed. Witnessed by Ita French	ORK DONE AND RES	at 200° and cented dry and all o bottom again the drilling	owed to to determines then
12½" 40# 8-Thd. New Eapweld casing was the Halliburton Method with 200 sacka. Coment was drilled out of the casing are stand undisturbed for one hour. The being any water had accumulated. No water resumed. Witnessed by Ita French Royame	ork Done and res s set in this well a d the hole was bail eiler was then run t r had accumulated so Dwan Drilling Co. Company	at 200° and cented dry and all o bottom again the drilling	owed to to determines then
122" 40# 8-Thd. New Eapweld casing was the Halliburton Method with 200 sacka. Cement was drilled out of the casing ar stand undisturbed for one hour. The be if any water had accumulated. No water resumed. Witnessed by Ita French Ro Name	ork Done and res s set in this well a the hole was bail alter was then run to the had accumulated so the bound of the bound of the bail Thereby swear or affinis true and correct	ut 200° and cented dry and all o bottom again the drilling Tool-pu	owed to to determines then
122" 40# 8-Thd. New Eapweld casing was the Halliburton Method with 200 sacka. Cement was drilled out of the casing ar stand undisturbed for one hour. The be if any water had accumulated. No water resumed. Witnessed by Ita French Ro Name	ork Done and res s set in this well a the hole was bail the hole was bail the had accumulated so to be company I hereby swear or affinis true and correct Name Position Farm Bos	ults OBTAINE at 200° and cen ed dry and all o bottom again the drilling Tool-pu em that the informa	owed to to determine then sher Title
12½ 40# 8-Thd. New Eapweld casing was the Halliburton Method with 200 sacka. Cement was drilled out of the casing ar stand undisturbed for one hour. The be if any water had accumulated. No water resumed. Witnessed by Ita French Name Subscribed and sworn to before e this	ork Done and res s set in this well a the hole was bail aller was then run to the had accumulated so to be company I hereby swear or affinis true and correct Name La	ults OBTAINE at 200° and cen ed dry and all o bottom again the drilling Tool-pu em that the informa	owed to to determine the to determine the trible tion given above
122 40# 8-Thd. New Eapweld casing was the Halliburton Method with 200 sacka. Coment was drilled out of the casing ar stand undistubbed for one hour. The be if any water had accumulated. No water resumed. Witnessed by Ita French Ro Name Subscribed and sworn to before e this	ork Done and res s set in this well a the hole was bail the hole was bail the had accumulated so the bound by the bound of the bound	at 200° and cented dry and all o bottom again the drilling Tool-put	owed to to determine the to determine the trible tion given above
122 40# 8-Thd. New Eapweld casing was the Halliburton Method with 200 sacka. Coment was drilled out of the casing ar stand undistubbed for one hour. The be if any water had accumulated. No water resumed. Witnessed by Ita French Ro Name Subscribed and sworn to before e this	ork Done and res s set in this well a the hole was bail the hole was bail the had accumulated so the bound by the bound of the bound	at 200° and cented dry and all o bottom again the drilling Tool-pu The drilling Tool-pu	owed to to determine the to determine the trible tion given above