

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NO. OF COPIES RECEIVED	
DISTRIBUTION	
DATE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES OF REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL, RE-DRILL, OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of operator
Amerada Hess Corporation
3. Address of operator
Drawer "D", Monument, New Mexico 88265
4. Location of Well
UNIT LETTER **N** **330** FEET FROM THE **South** LINE AND **2310** FEET FROM THE **West** LINE, SECTION **33** TOWNSHIP **19-S** RANGE **37-E** NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

7. Unit Agreement No.
8. Form or Lease No.
S. Phillips
9. Well No.
1
10. Field and Pool, or
Monica-Monument
12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐ REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐ OTHER ☐ CASING TEST AND CEMENT JOB ☐
OTHER ☐ ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to: Drill out cement and CIBP at 3693'. Set CIBP and plug back with cement to 3735'.
Perforate G-SA selectively from 3694' to 3732'. Acidize with 1500 gals.
15% acid. Swab test & restore well to producing status.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ED *[Signature]* TITLE Supver., Admin. Services DATE 4-2-75
APPROVED BY *[Signature]* TITLE DATE
CONDITIONS OF APPROVAL, IF ANY: DATE