State of New Mexico

Form C-103 Submit 3 Copies Energy, Minerals and Natural Resources Department Revised 1-1-89 to Appropriate District Office OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-025-05834 DISTRICT II Santa Fe. New Mexico 87504-2088 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 STATE FEE 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 B - 274SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: East Eumont Unit WEIL XOTHER WELL 2. Name of Operator 8. Well Na Sirgo Operating, Inc. 9. Pool name or Wildcat 3. Address of Operator PO Box 3531, Midland, TX 79702 Eumont-Yates-SR-Q 4. Well Location : 660 Feet From The North Line and 1980 Feet From The East Line 37E -- NMPM Lea Township 19S County Section Range 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3594' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING TEST AND CEMENT JOB Temporarily Abandon OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 7-14-92 MIRU PU. POH w/rods, pump & tbq. RIH on wireline 7" CIBP. Set CIBP @ 3720'. Fill casing to surface with treated fluids.

·		
· · · · · · · · · · · · · · · · · · ·		
I hereby certify that the information above is true and comprise to the best of my know	wkedge and belief	7-22-92
TYPEOR PRINT NAME Victor J. Sirgo		915/685-0878 Telephone no.
(This space for Stat DRIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR APPROVED BY	πu	JUL 28 19

Move all equipment off location and clean up.