

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO.  
30-025- 05850  
5. Indicate Type of Lease  
STATE ☒ FEE ☐  
6. State Oil & Gas Lease No.  
B2330

7. Lease Name or Unit Agreement Name:  
East Eumont Unit

8. Well No.  
108

9. Pool name or Wildcat  
Eumont Yates 7Ror Qn

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
OXY USA Inc. 16696

3. Address of Operator  
P.O. BOX 50250 MIDLAND, TX 79710-0250

4. Well Location  
Unit Letter D : 660 feet from the North line and 660 feet from the West line  
Section 1 Township 20S Range 37E NMPM LEA County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3603'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
MULTIPLE COMPLETION <input type="checkbox"/>	OTHER: <input type="checkbox"/>
OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU PU 12/29/98, TEST ANCHORS, NDWH, NUBOP. RIH W/ OVERSHOT & TAG @ 3267', ATTEMPT TO LATCH ONTO FISH, W/O SUCCESS, POOH. RIH W/ BIT & TAG @ 3267', DRILL JUNK LOOSE, PUSH DOWN TO 3874', POOH. RIH W/ CIBP & SET @ 3791', DUMP 35' CMT ON TOP. RIH & TAG @ 3702', CIRC HOLE W/ 10# MUD, SPOT 25sx CL C CMT. POOH TO 2858', SPOT 25sx CL C CMT. POOH TO 1540', SPOT 25sx CL C CMT, POOH. RIH PERF 2 SQZ HOLES @ 658', EIR @ 3BPM @ 300#, POOH LD TBG, NDWH, NDBOP, M&P 175sx CL C CMT, CIRC CMT TO SURF BETWEEN 5 1/2" & 8-5/8" & INSIDE 5 1/2" CSG. RDPU 1/5/99, DUG OUT CELLAR, INSTALL DRY HOLE MARKER. NMOCN NOTIFIED & REVIEWED PLUGGING PROCEDURE W/ JOHNNY ROBINSON.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE REGULATORY ANALYST DATE 7/15/99

Type or print name DAVID STEWART Telephone No. 915-685-5717  
(This space for State use)

APPROVED BY [Signature] TITLE Field Rep DATE 4-24-01  
Conditions of approval, if any:

IC GWW

hew