	State of New Mexico	Form C-1
Office District I	Energy, Minerals and Natural Resources	Revised March 25, 19
1625 N. French Dr., Hobbs, NM 87240		WELL API NO.
District II 811 South First, Artesia, NM 87210	OIL CONSERVATION DIVISION	30-025-05855
District III	2040 South Pacheco	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	STATE FEE 🔀
2040 South Pacheco, Santa Fe, NM 87505		6. State Oil & Gas Lease No.
SUNDRY NOTI	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH	
1. Type of Well: Oil Well Gas Well	Other Injection	East Eumont Unit
2. Name of Operator	omer 400 EC	8. Well No.
OXY USA WIP Limited Partner	ship 19246	
3. Address of Operator		9. Pool name or Wildcat
P.O. Box 50250 Midland, TX	79710-0250	Eumont Yates 7Rvr On
4. Well Location		
Unit Letter G : 7	2310 feet from the North line and 2	310 feet from the east line
Section \	Township ZOS Range 37E	NMPM County Lea
	10. Elevation (Show whether DR, RKB, RT, GR, et	
	Appropriate Box to Indicate Nature of Notice,	Report, or Other Data
NOTICE OF INT	ENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	☐ ALTERING CASING
EMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLI	ING OPNS.
PULL OR ALTER CASING	MULTIPLE CASING TEST AND	ABANDONMENT
OLL ON ALIER CASING		
	COMPLETION CEMENT JOB	
OTHER:	COMPLETION CEMENT JOB OTHER: M.	
OTHER: 12. Describe Proposed or Complete	COMPLETION CEMENT JOB	ve pertinent dates, including estimated date
DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation.	COMPLETION CEMENT JOB OTHER: M od Operations (Clearly state all pertinent details, and gi	ive pertinent dates, including estimated date wellbore diagram of proposed completion
DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to	COMPLETION OTHER: OTHER: Od Operations (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach	ve pertinent dates, including estimated date wellbore diagram of proposed completion future use.
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3941' PBTD-39	COMPLETION CEMENT JOB OTHER: Od Operations (Clearly state all pertinent details, and gi SEE RULE 1103. For Multiple Completions: Attach to temporarily abandon this well for possible Perfs-3824-3894 Pkr/	ive pertinent dates, including estimated date wellbore diagram of proposed completion
DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3941 PBTD-39	COMPLETION OTHER: OTHER: Od Operations (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach	ve pertinent dates, including estimated date wellbore diagram of proposed completion future use.
DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3941' PBTD-3941' PBT	COMPLETION CEMENT JOB OTHER: OTHER:	ive pertinent dates, including estimated date wellbore diagram of proposed completion future use.
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3941 PBTD-39	COMPLETION CEMENT JOB OTHER: OTHER:	ive pertinent dates, including estimated date wellbore diagram of proposed completion future use.
DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3941' PBTD-3941' PBT	COMPLETION CEMENT JOB OTHER: OTHER: Od Operations (Clearly state all pertinent details, and give see RULE 1103. For Multiple Completions: Attach of temporarily abandon this well for possible perfs-3824-3894 Perfs-3824-3894 Perfs-3824-3894 Pkr/ sing integrity test 24hrs in advance. L, circulate well with treated water, pressurin. This Approval of Temporary	ive pertinent dates, including estimated date wellbore diagram of proposed completion future use.
DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3941' PBTD-3941' PBT	COMPLETION CEMENT JOB OTHER: OTHER:	ive pertinent dates, including estimated date wellbore diagram of proposed completion future use.
DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3941 PBTD-39 1. Notify BLM/NMOCD of cas 2. RU pump truck 5 29 02 to 510 # for 30 m	COMPLETION CEMENT JOB OTHER: OTHER:	we pertinent dates, including estimated date wellbore diagram of proposed completion future use. -3768 ure test casing
DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD- 3941 PBTD- 3941 PBT	COMPLETION CEMENT JOB OTHER: OTHER: Od Operations (Clearly state all pertinent details, and give see RULE 1103. For Multiple Completions: Attach of temporarily abandon this well for possible perfs-3824-3894 Perfs-3824-3894 Perfs-3824-3894 Pkr/ sing integrity test 24hrs in advance. L, circulate well with treated water, pressurin. This Approval of Temporary	we pertinent dates, including estimated date wellbore diagram of proposed completion future use. -3768 ure test casing
DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3941 PBTD-39 1. Notify BLM/NMOCD of case to 510 # for 30 mereby certify that the information above in the complete of the complete	COMPLETION CEMENT JOB OTHER: OTHER:	we pertinent dates, including estimated date wellbore diagram of proposed completion future use.
DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD- 3941 PBTD- 39 1. Notify BLM/NMOCD of case 2. RU pump truck 5 29 02 to 510 # for 30 mereby certify that the information above in the complete of t	COMPLETION CEMENT JOB OTHER: OTHER:	we pertinent dates, including estimated date wellbore diagram of proposed completion future use. -3768 ure test casing DATE 61002
DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3941 PBTD-39 1. Notify BLM/NMOCD of cas 2. RU pump truck 5 29402 to 510 # for 30 m ereby certify that the information above in the constitution of the constitut	COMPLETION CEMENT JOB OTHER: OTHER:	we pertinent dates, including estimated date wellbore diagram of proposed completion future use.
DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3941 PBTD-39 1. Notify BLM/NMCD of cas 2. RU pump truck 5 29402 to 510 # for 30 m ereby certify that the information above in the constitution of the constituti	COMPLETION CEMENT JOB OTHER: OTHER:	we pertinent dates, including estimated date wellbore diagram of proposed completion future use. P-3768 ure test casing DATE 61002 Telephone No. 915-685-5717
DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3941 PBTD-39 1. Notify BLM/NMOCD of cas 2. RU pump truck 5 29 02 to 510 # for 30 m	COMPLETION CEMENT JOB OTHER: OTHER:	we pertinent dates, including estimated date wellbore diagram of proposed completion future use. -3768 ure test casing DATE 61002

