|  | · ·  |
|--|--|
| NO. OF COPIES RECEIVED   | Face C 102                                   |
| HOBBS OFFICE O. C.C.   | Form C-103<br>Supersedes Old                 |
|  | C-102 and C-103<br>Effective 1-1-65          |
| FILE NEW MEXICO OIL CONSERVATION COMPASSION  | 211 31113 1 1 113                            |
| U.S.G.S.   | 5a. Indicate Type of Lease                   |
| LAND OFFICE  | State Fee. X                                 |
| CPERATOR   | 5, State Dil & Gas Lease No.                 |
|  |  |
| SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)                                      |  |
| I. OIL X SAS OTHER-  | 7, Unit Agreement Name                       |
| 2. Name of Operator  | 8, Farm or Lease Name                        |
| Humble Oil & Refining Company 3. Address of Operator   | M. E. Laughlin                               |
| Box 1600, Midland, Texas   | 9. Well No.                                  |
| 4. Location of Well  | 10. Field and Pool, or Wildcat               |
| UNIT LETTER  | Monument                                     |
|  |  |
| THE West LINE, SECTION 4 TOWNSHIP 20-S RANGE 37-E  | MPM. Alliilliilliilliillii                   |
|  |  |
| 15. Elevation (Show whether DF, RT, GR, etc.)  | 12. County                                   |
| 3570 DF  | Lea  |
| Check Appropriate Box To Indicate Nature of Notice, Report or NOTICE OF INTENTION TO:  SUBSEQU   | Other Data ENT REPORT OF:                    |
| PERFORM REMEDIAL WORK Y  | ALTERING CASING                              |
| TEMPORARILY ABANDON COMMENCE DRILLING OPNS.  | PLUG AND ABANDONMENT                         |
| PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB   | _  |
| OTHER  |  |
|  |  |
| 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incluwork) SEE RULE 1103.  | ding estimated date of starting any proposed |
| Pull rods & tbq. Test casing for leaks. If leak located, co-<br>casing or run liner. If no leak located, run radioactive tr<br>locate water source. Repair by squeeze cementing. Drill out<br>Stimulate and test. Return well to production. | racer to                                     |
|  | •  |
| 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.   |  |
| SIGHED Agent   |  |
|  |  |

CONDITIONS OF APPROVAL, IF ANY