

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

3-NMOCC ✓  
 1-R.J. STARRAK-TULSA  
 1-A.B. CARY-MIDLAND  
 1-MYM, ENGR.

1-BI, FOREMAN  
 1-FILE  
 1-BH, FIELD CLERK

Form C-101  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                                                                                                                                                               |                                                                                                                                                         |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>SUNDY NOTICES AND REPORTS ON WELLS</p> <p>DO NOT USE THIS FORM FOR NOTICES TO LESSEES OR TO OTHERS OR FOR LACK OF A DIFFERENT RESERVOIR.<br/>         USE SEPARATE FORM FOR REPORTS ON WELLS FOR EACH DIFFERENT RESERVOIR.</p>                                                                                                                                                                                                                                    |                                                                                                                                                                               | <p>5a. Indicate Type of Lease</p> <p>State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil &amp; Gas Lease No.</p> |
| <p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER</p> <p>2. Name of Operator</p> <p>Getty Oil Company</p> <p>3. Address of Operator</p> <p>P. O. Box 703, Hobbs, New Mexico 88240</p> <p>4. Location of Well</p> <p>UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>4</u> TOWNSHIP <u>20</u> RANGE <u>37</u> NMPH.</p> | <p>7. Unit Agreement Name</p> <p>8. Name of Lessee Name</p> <p>M. E. Laughlin</p> <p>9. Well No.</p> <p>2</p> <p>10. Field and Pool, or Wildcat</p> <p>EU-MON GRAYBURG SA</p> |                                                                                                                                                         |
| <p>15. Elevation (Show whether DF, KT, GR, etc.)</p> <p>3561 PR</p>                                                                                                                                                                                                                                                                                                                                                                                                  | <p>12. County</p> <p>Lea</p>                                                                                                                                                  |                                                                                                                                                         |

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |  |                              |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|------------------------------|--|
| <p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p> <p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> OTHER <input type="checkbox"/></p> <p>OTHER <u>Return to production</u></p> |  |  |  | <p>SUBSEQUENT REPORT OF:</p> |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|------------------------------|--|

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Rig up pulling unit.
  - Pull rods and pump.
  - Install BOP & pull tubing.
  - Go in hole with bridge plug and packer and set BP at 3800' on tubing. Dump 2 sxs sand on top of BP.
  - Spot 200 gals. 15% HCL from 3600-3800' and TOH.
  - Rig up Western Wireline and perforate 1 spf, selectively, using 3 1/8" Posijet Premium Gun, avg. penetration 15.36", 0.34" hole size.
- 3628', 3687', 3648', 3652', 3654', 3659', 3662', 3668', 3676', 3678', 3687',  
 3691', 3697', 3707', 3712', 3722', 3730', 3734', 3740', 3744', 3763', 3769',  
 3772', 3778', 3785', & 3791' (Total of 26 holes).
- Swab test the new perforations.
  - If test dry, by Runco acidize with 2800 gals. 15% HCL acid using 50 ball sealers. Maintain enough injection rate to ball out. Use 2% KCL water for flush.
  - Swab test for production.
  - If test low water-oil ration, return to pumping.
  - If high water-oil ratio, pull BP and put new and old (bottom) pay on pump.
  - Test for stabilized production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Neil R. Crockett TITLE Area Superintendent DATE 12-11-78

DATE R. Crockett

Orig. Signed by John Runyan TITLE Geologist DATE DEC 13 1978

APPROVED BY John Runyan TITLE Geologist DATE DEC 13 1978

CONDITIONS OF APPROVAL, IF ANY