

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS	<input checked="" type="checkbox"/>	REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

July 15, 1953

(Date)

Hobbs, New Mexico

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Cities Service Oil Company

Laughlin

(Company or Operator)

(Lease)

J. C. Crain Drilling Company

5

SW

SE

5

(Contractor)

, Well No. in the 1/4 of Sec.

T. 20S, R. 37E, NMPM., Undesignated Pool, Lea County.

July 14, 1953

The Dates of this work were as follows:

C-101

July 7

Notice of intention to do the work (was ~~not~~) submitted on Form ~~C-102~~ on 1953

(Cross out incorrect words)

and approval of the proposed plan (was ~~not~~) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Laughlin #5 was spudded at 1:00 PM on 7-14-53.

Witnessed by C. E. Hartwell Cities Service Oil Company District Superintendent  
(Name) (Company) (Title)

Approved: OIL CONSERVATION COMMISSION

Roy Yachnovich  
(Name)  
Oil & Gas Inspector  
(Title)  
401 17 1953  
(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name: Charles M. Harbuck  
Position: District Superintendent  
Representing: Cities Service Oil Company  
Address: Box 77, Hobbs, New Mexico