

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.

30-025-05911

Indicate Type of Lease

STATE ☒

FEE ☐

State Oil & Gas Lease No.

033250

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Lease Name or Unit Agreement Name

Bertha Barber

Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

Name of Operator

Marathon Oil Company

Well No.

6

Address of Operator

P.O. Box 2490 Hobbs, New Mexico 88241

Pool name or Wildcat

Eurnont, Yates, 7 Rivers, Queen

Well Location

Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line

Section 5 Township 20-S Range 37-E NMPM Lea County

Elevation (Show whether DF, RKB, RT, GR, etc.)

GL 3559 KB 3570

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ANBANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

03/18/99--Notify OCD of intent to plug

03/19/99--MIRU, TIH w/7" CICR, retainer set @ 1235'

03/22/99--Okayed by OCD to pump cement from 1235' below retainer, pump 500 sx C cement below retainer
w/2 % CaCl in last 150 sx, SION

03/23/99--Plug fm 2884-3349' (calculated), pumped 58 bbls & test @ 1000 PSI, spot 10 sx @ 1235', reverse
out @ 1173', Mix and circulate mud to surface, perf @ 1155', unable to pump into perms, spot 25 sx
(per OCD) @ 1155-1002', perf @ 192', break circulation out braiden head, pump 75 sx cement
to surface out braiden head, leave 7" full, RDMO

03/25/99--Cut off well head, install dry hole marker, clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Terry McBeth

TITLE Supervisor, Key Energy, P&A Division

DATE 03-25-99

TYPE OR PRINT NAME Terry McBeth

TELEPHONE NO. (915) 523-5155

(This space for State Use)

APPROVED BY

JOYCE WILLIAMS
DISTRICT SUPERVISOR

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

my