NO. OF COPIES RECEIVED		•	Form C-103
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION		Supersedes Old C-102 and C-103
SANTA FE			Effective 1-1-65
FILE	1		
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE	1		State Fee. X
OPERATOR	1		5, State Oil & Gas Lease No.
SCIALIS	DY MOTICES AND REPORTS ON	WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "PAPPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
1.			7. Unit Agreement Name
OIL X GAS WELL	OTHER-		
2. Name of Operator			8. Farm or Lease Name
Marathon Oil Company			Bertha Barber
3. Address of Operator			9. Well No.
	. Box 220, Hobbs, New Mex	ico 88240	8
4. Lucation of Well			10. Field and Pool, or Wildcat
			Monument Grayburg
UNIT LETTER E , 1980 FEET FROM THE NORTH LINE AND 660 FEET FROM			777777777777777777777777777777777777777
17	5 200	275	
THE WEST LINE, SECTS	ton 5 TOWNSHIP 20S	RANGE J/L NMPM.	
comment of the second	15. Elevation (Show whether	DE RT CR etc.)	12. County
		9' KDB	Lea
<u> </u>			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANCONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		other Temporary	Abandoned x
OTHER			
			The state of the s
17. Describe Proposed or Completed Operate work) SEE RULE 1103.	perations (Clearly state all pertinent dete	tils, and give pertinent dates, including	estimated date of starting any proposed
,			
TD 3900'. Set cement retainer @ 3751' and squeezed perfs. in 7" csg. from 3756-3766'			
with 200 sacks cement.			
Perf. Grayburg @ 3722,23,24,25,44,45,46, & 47. Pumped 120 gals. acid into perfs.			
Set cement retainer @ 3722' and squeezed perfs. in 7" csg. from 3732-3747' w/60 sks cement.			
Perf. 7" csg. @ 3694 to 3703 & 3712-3713' and treated with 1300 gals. 15% acid.			
Set cement retainer @ 3688' and pumped 57 sks in formation. Attempted to released stinger			
from retainer. Unab	ble to pull stinger. Dur	ing attempts to back of	E tbg. to bottom, 42
its. of 2-7/8" tbg. full of cement were recovered and the tbg. and hole cleaned out to			
3395' with 293' of fish $(2-7/8'')$ tbg. full of cement) still in hole.			
33,3		•	
Operations suspended. Well temporary abandoned.			
operations suspended	1. Well tempolary arango		
Prior to workover to	o recomplete higher in Gr	avburg, well was product	ing 4 BOPD and 238
BSWPD by gas lift.	J 1000mp1000 H18H01 III 01	, 5 0.18, p. 10 11 11	8
nowed by gas ille.			
			
15. I hereby certify that the information	n above is true and complete to the best of	or my knowledge and belief.	
/ / dl: no	'		
SIGNED (, D. COLLE	TITLE	Area Supt.	DATE 1-23-70
1/2 ~ 1/		A	
APPROVED BY	Have 1 TITLE		DATE
-/			
CONDITIONS OF APPROVAL, IF AN	·		