OIL CONSERVATION COM' ISION Santa Fe, New Mexico

REQUEST FOR (OIL)-(GAS) ALLOWABLE

It is necessary that this form be submitted by the operator before an initial allowable will be assigned to any completed oil or gas well. Form C-110 (Certificate of Compliance and Authorization to Transport 0il) will not be approved until Form C-104 is filed with the Commission. Form C-104 is to be submitted in triplicate to the office to which Form C-101 was sent. Two copies will be retained there and the other submitted to the Proration Office, Hobbs, New Mexico. The allowable will be assigned effective 7:00 a.m. on date of completion, provided completion report is filed during month of completion. The completion date shall be that date in the case of an oil well when oil is delivered into the stock tanks. Gas must be reported on 15.025 P.B. at 60° Fahrenheit.

Hot	bbs, No	Maxico	.ce	J	aly 11, 1952			
Place			.ce	Date				
WE ARE HE	REBY REC	OUESTING	AN ALLOWABLE FOR A	WET I KNOWN	AC.			
The Ohio	Oil Con	pary	Bertha Barber	Well N	o. 9 in Sw	1/4_M	1/	
Ud	отрапу с	or Operat	or Lease					
section	5,	T. 205	R. 37E ,N.M.P.	Monument-	Blinebry	Lea	Cou	
	,	,					COU	
Please inc	dicate 1	location:	Elevation 3571	Spudded	5/28/52 Comr	leted 7	/6/52	
r			Total Depth					
]			Top 0il/Ggg Pay_ Initial Production	5662	Top Water Pay_			
			Initial Production	on Test: Pum	p Flow	821	BOPD OR	
C			Based on 206 Bb	ols. Oil in_	6 Hrs	-	Mi	
			Method of Test (F					
			Size of choke in					
			Tubing (Size)				F	
			Pressures: Tubin					
			Gas/Oil Ratio			38 €	60	
				Casing Pe	erforations:			
Unit lett	eri	E	5664 to 5687 a	and 5694 to !	5705			
Size	[Sax 250	Gals Gals Shooting Record.	to	S/ S/			
			04	4.	S/			
8-5/8	2801	1200	Qts	to	S/			
		-4-	Qts	to	S/			
5-1/2	5752	515			5/			
0.0/0	7700							
2-3/8	5720		Test after acid o	r \$1/d/\frac{1}{2}:	Pumping	x	_ Flow:	
5-1/2 2-3/8	5752 5720	515		Shooting Record. Qts Qts Qts Natural Productio Test after acid o	Shooting Record. Qts to Qts to Natural Production Test: Test after acid or \$1675:	Shooting Record.	Shooting Record.	
1		elow Form						
	-		ern New Mexico	Ormanice Will.	Northweste			
• Anhy			T. Devonian		T. Ojo Alamo			
Salt					T. Kirtland-	Fruitland		
3. Salt					T. Farmington			
ľ.Yates _			T. Simpson			Cliffs		
			T. McKee		T. Cliff House	se		
r. Queen					T. Menefee			
Graybur	g		T. Gr. Wash					
San And								
Glorieta								
f. Drinkar r. w <i>AAAA</i> G		5100			T. Morrison			
Γ. Abo					T. Penn			
. Penn					T			
. Miss			т.		1• η			

ate first oil run to	tanks or gas to pipe line: July 10, 1952
ipe line taking oil o	r gas: Texas New Mexico Pipe Line Company
lemarks:	•
	The Ohio Oil Company Company or Operator
	By:
	D. Alabama B. A. A. A. A.
	Position: Superintendent
Send communications re	egarding well to:
	Name: The Ohio Oil Company
	Address: P. O. Box 2107
	Hobbs, New Mexico
APPROVE	ID
OIL CO	NSERVATION COMMISSION
By:	Post Bin m