•			
NO. OF COPIES RECEIVED DISTRIBUTION SANTA FE FILE U.S.G.S. LAND OFFICE OPERATOR	NEW MEXICO OIL CONS	SEP 15 11 34 11 365	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 Sa. Indicate Type of Lease State Fee 5. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PR USE "APPLICAT 1. OIL GAS WELL WELL	RY NOTICES AND REPORTS ON DPOSALS TO DRILL OR TO DEEPEN OR PLUG I TON FOR PERMIT (FORM C-101) FOR SUC	WELLS BACK TO A DIFFERENT RESERVOIR. CH PROPOSALS.)	7. Unit Agreement Name
2. Name of Operator Sum Oil Company 3. Address of Operator Box 2792, Odessa, Texas 4. Location of Well			8. Farm or Lease Name <u>M. E. Laughlin</u> 9. Well No. 2
UNIT LETTER	990 FEET FROM THE South ON 5 TOWNSHIP 205	_	
15. Elevation (Show whether DF, RT, GR, etc.)			12. County
	Appropriate Box To Indicate N NTENTION TO:	-	Other Data NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
17 Describe Despected or Completed Or			ng estimated date of starting any proposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled rods and pump. Installed BOP, pulled tbg., reran tbg. w/csg. scraper to 3750[•]. Pulled scraper and reran tubing w/Baker Model R-2 pkr. to 3690[•]. Squeezed open hole under Baker R-2 packer set at 3690[•] w/100 sks Incor neat cement, wt. $14^2 - 14^5$ - over flushed w/6½ bbls. water Squeezed open hole w/100 sks Incor, reversed out appx. 50 sks cement, pulled 500[•] tubing, shut down, WOC. Movved in reverse unit and tested cement, 800#, 15 min., o.k. Pulled tubing, reran w/pkr and w/bit and csg. scraper, checked top of cement at 3689[•]. Drilled cement to 3750[•], circulated hole, tested $5\frac{1}{2}$ [#] casing, 500# 30 min. e.k. Lane Wells checked cement plug at 3760[•], perforated $5\frac{1}{2}$ [#] & 7[#] casing, w/1 JSPF from $(3702-3742^{•})$ w/NCF-2 charge by PGAC. Gamma Ray Log. Ran Baker h-2 packer on $2\frac{1}{2}$ [#] tbg. Tubing seat $3750^{•}$, packer 3678[‡] Swabbed. Cardinal acidized dawn $2\frac{1}{2}$ [#] tbg. w/250 gals., MEC acid spotted 2 bbls. acid across perfs. and let soak. Displaced acid into formation in 1 bbl. stages. Reset packer, @ 3584[‡], tubing seat 3656[‡]. Swabbing. Cardinal acidized perfs. $3702-3742^{•}$ w/2000 gals. 15% LST acid w/49 ball sealers down $2\frac{1}{2}$ [#] tubing, seat 3656[‡], packer 3584[‡]. Pulled packer and reran tubing and rods. Tubing seat 3725[‡], seating nipple 3690[‡]. 24 hour potential test ending 9-10-65, 24.85 bbls. oil, 26.21 bbls. water, GOR 21235/1.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
STGNED U. L. Clicist	TITLE Area Superintendent	DATE		
		DATE		

CONDITIONS OF APPROVAL, IF ANY: