

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
COPY DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER ☐
Name of Operator
Texaco Inc.
Address of Operator
P. O. Box 728, Hobbs, NM 88240
Location of Well
UNIT LETTER D 736 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 6 TOWNSHIP 20S RANGE 37E N.M.P.M.

7. Unit Agreement Name
8. Farm or Lease Name
J. R. Phillips
9. Well No.
11
10. Field and Pool, or Wildcat
Monument McKee
Ellenburger

15. Elevation (Show whether GF, RT, GR, etc.)
3585' DF
12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Rig up Knox services on tbq. Treated 5½" csg. perfs @ 9490-9751' w/3000 gal 15% NEFE acid, 100 ball sealers, and 500# rocksalt. Max. pressure 5000#, AIR 7.5 BPM. Flushed w/2% KCL. Job completed 02/21/86.
- 2) MIRU Swab unit. Swabbed 5 hrs. Open to sales line.

I hereby certify that the above is true and complete to the best of my knowledge and belief.
SIGNED J. W. Browning TITLE District Admin. Supervisor DATE 04/14/86
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR
DATE APR 24 1986