

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-025-05965
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Phillips, J.R.
8. Well No. 12
9. Pool name or Wildcat Yates, 7 Rvrs, Queen
10. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Texaco Exploration & Production, Inc.

3. Address of Operator

P. O. Box 3109, Midland, TX 79705

4. Well Location

Unit Letter F : 2269 feet from the North line and 2266 feet from the West line

Section 6 Township 20S Range 37E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set 5 1/2 CIBP @ 2975' (Yates-Queen) spot 40 Sx plug 2975'-2700' (B-Salt 8 5/8 shoe) Tag Cmt @ 2618'
2. Displace hole w/MLF 9.5# Brine w/25# gel P/BBL
3. Spot 50 Sx plug 1418'-1100' (T-Salt) Tag Cmt @ 951' (On 2/26/95 Sqz & Circ Cmt w/250 Sx to Surf)
4. Spot 25 Sx plug 400'-200' (13 3/8" shoe) Tag Cmt @ 182'
5. Circ Cmt 30' to Surf w/15 Sx. Install dry hole marker. 8/2/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER DATE 8/2/01

Type or print name Jimmy BAGLEY Telephone No. 915 683-4996
(This space for State use)

APPROVED BY [Signature] TITLE Fld Rep DATE 10-18-01
Conditions of approval, if any:

K2 GWW

