			an a				
NO. OF COPIES	RECEIVED	· · · · · · · · · · · · · · · · · · ·			1. L.	Form C-103	
DISTRIBUTION				۰	14. 4 •	Supersedes Old	
SANTA FE			Orige 2cc: OC, Hobbe			C-102 and C-10 Effective 1-1-65	
FILE		Orig&2cc	: OCC, Hobbs	SEP	06 1.1		
U.S.G.S.	· · · · · · · · · · · · · · · · · · ·		: West Texas Re	gion		5a. Indicate Type o	of Lease
LAND OFFICE	E	cc	cc: file			State	Fee.
OPERATOR						5. State Oil & Gas	Lease No.
	ł						
			AND REPORTS ON	WELLS			
(DO NOT	USE THIS FORM	FOR PROPOSALS TO DRIL	L OR TO DEEPEN OR PLUG BA	CK TO A DIFFERENT RES	SERVOIR.		
1.						7. Unit Agreement	Name
OIL WELL	GAB Well	OTHER-	into Allera Effortiva M	ರ ಪಿಸಲವೆ ೧೯೭೫ ಕನ್ನಾರಿದ್ದಾರೆ. ಆಟರ್ಟ್ ೧೯೯೯ರಲ್			
2. Name of Opera	SINCE	IR OIL COL	SINELAIR OU	<u> </u>		8. Farm or Lease 1 Bertha J	
3. Address of Op				- Arokanci	· · · · · · · · · · · · · · · · · · ·	9. Well No.	
	P. O.	Box 1920, Hobb	s, New Mexico		-	2	
4. Location of We	ell	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·			10, Field and Pool	i, or Wildcat
	A	330'	North		90	Monument	
UNIT LETTER		- , <u></u> , PEC	FROM THE	LINE AND	FEET FROM	<u>uuuuuu</u>	viinnin.
THEE		E, SECTION	205	RANGE	37E NMPM.		
	mm	15.	Elevation (Show whether i	DF, RT, GR, etc.)		12. County	
				74' DF		Lea	
	mm					I	<u></u>
			Box To Indicate N				
•	NOTICE	OF INTENTION T	0:		SUBSEQUENT	REPORT OF:	
							
PERFORM REMEDI	Ħ		PLUG AND ABANDON	REMEDIAL WORK			NG CASING
TEMPORARILY AB				COMMENCE DRILLING		PLUG AN	ID ABANDONMENT
PULL OR ALTER C			CHANGE PLANS	CASING TEST AND CEM			
				OTHER		······································	
OTHER			······································				
work) SEE R	RULE'1103.		ly state all pertinent deta				
8-13 -6 6	Cement s	squeezed Graybu	rg perforations	1 3752-75° w/1	00 sks. Cla	ass "C" neat	cement
	preceded	l by 200 gals.	726 MCA Max. Pr	ess. 4000#, r	eversed 15	sks.	~ /~~~
8-14-66	Jet peri	Corate 6-5/8"OD	casing @ 3430	w/4-3/8" hole	s, acidized	l perfs. 343	0" w/250
	gass. 7	3% MCA, broke	3800#, avg inj	. rate 1500#,	2 BPM.		
8-15-66			.001 and squeeze		sing peris.	, @ 3430' ₩/	LUU SKS. CLASS
			sed 20 sks. WC			5	
8-16-66), cement @ 3415				rested
A 9 - 11			1430' to 1500# f				-1 -7 4
8-18-66	Jet perf. Grayburg 3670-80' w/20-3/8" jet shots, M.A. wash perfs. w/500 gals. BDA, Max. Press. 3300#, Min. Press. 1600# @ 4 BPM. Inst. SIP 700#, vacuum in, 2 mins.						
0 0 11	Max. Pre	ss. 3300#, Mir	. Press. 1600#	W 4 BPM. Ins	τ. SIP 700	7, vacuum in	, 2 m1~3.
8-21-66 Ran 2-7/8"OD EUE tubing and seat nipple to 3639!, ran rods and placed on pumping 9-7-66 Pumped Grayburg perfs. 3670-80!, 114 BFW, trace dead oil and TSTM show of gas in						pumping test	
9-7-66	24 hrs,	Shut-in, reco	mpletion attemp	orw, trace de ot unsuccession	il. Held Fo	or Future De	velopment.

18. I hereby certify that the information above is true and complete to the best of t	ny knowledge and belief.			
SIGNED TITLE	Superintendent	DATE	9-9-66	

		. (j. 1 4)
APPROVED BY	TITLE	DATE

CONDITIONS OF APPROVAL, IF ANY: