

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-025-06001

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name T. Anderson
2. Name of Operator Amerada Hess Corporation	8. Well No. 1
3. Address of Operator P. O. Box 840, Seminole, Texas 79360	9. Pool name or Wildcat Eumont Yates 7RQ
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>8</u> Township <u>20S</u> Range <u>37E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-11-98 thru 1-5-99

MIRU Tyler Well Svc. pulling unit. Removed wellhead, installed BOP & TOH w/tbg. & pkr. TIH w/5-7/8" bit to 3155' & TOH. Schlumberger TIH w/4" Hags csg. guns & perf. Eumont Zone w/4 SPF, total 208 shots at following: 3060' - 3070', 3090' - 3110', 3116' - 3125', & fr. 3133' - 3145'. American Fracmaster acidized Eumont Zone perfs. fr. 2830' - 3145' w/2650 gal. 15% HCL acid. Removed BOP, replaced wellhead, & re-installed BOP. TIH w/2-3/8" tbg. set OE at 3147'. Removed BOP & installed wellhead. Swabbed well. RD swab unit & cleaned location. left well open w/0# press. 9-20-98: MIRU Tyler Well Svc. pulling unit. Removed wellhead, installed BOP & TOH w/tbg. TIH w/6-5/8" Md. "G" RBP on 2-3/8" tbg. & set RBP at 3130'. Pulled tbg. up hole to 3100'.
CONTINUED OVER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roy L. Wheeler, Jr. TITLE Bus. Svc. Spec. II DATE 1-8-99

TYPE OR PRINT NAME Roy L. Wheeler, Jr. TELEPHONE NO. 915 758-6700

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Removed BOP & installed wellhead. RDPU & cleaned location. RU swab unit & swabbed well. No production. RD swab unit & closed in well 9-24-98.
10-15-98: MIRU Tyler Well Svc. pulling unit. Released RBP & reset at 3080', set tbg. OE at 3049'. Swabbed well to 10-23-98 & closed in. 12-2-98: TOH w/tbg. & RBP. RDPU & cleaned location. Closed in well.

1999