Submit 3 Copies To Appropriate Dis	Strict				
Office State of New Mexico				Form C-103	
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240			Revised March 25, 1999 WELL API NO.		
District II 1301 W. Grand Avenue, Artesia, NM 88210 OIL CONSERVATION DIVISION			30-025-06043		
District III			5. Indicate Type of Lease		
District IV Santa Fe NM 87505			STATE		
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil &	Gas Lease No.	
SUNDRY	NOTICES AND REPORTS	ON WELLS	7 Loose Name	TI to a	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name: L. Van Etten		
PROPOSALS.) 1. Type of Well:			L. van Etten		
Oil Well Gas Well Gas Well Gas Well					
2. Name of Operator Chevron USA, Inc.					
			8. Well No.	8. Well No.	
3. Address of Operator 15 Smith Rd. Midland, Tx 79705			9. Pool name or Wildcat		
4. Well Location			Monument Paddock		
Unit Letter N	feet from the	e south line and 1	980 feet fro	om the west line	
Section 9	T 1: '		icet in	om the west line	
Section 5	Township 2		NMPM	County Lea	
		whether DR, RKB, RT, GR,			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
SIB			BSEQUENT RE	Data SDODT OF.	
PERFORM REMEDIAL WOR	K PLUG AND ABANDO	N REMEDIAL WO	RK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE			
COMMENCE DRI			RILLING OPNS.	LLING OPNS. PLUG AND ABANDONMENT	
FOLL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST	AND 🗀	ABANDONMENT	
OTHER.	COMI ELTION	CEMENT JOB			
OTHER:		OTHER:			
12. Describe proposed or co	ompleted operations. (Clear	ly state all pertinent details, a	nd give pertinent dat	es, including estimated date	
or recompilation.	, = 1135, 101	Maniple Completions. Ana	ch wellbore diagram	of proposed completion	
1. Set 4 1/2 CIBP @ 5040, spot 25sx plug fr/5040-4800/Poddock) Tex @ 4700					
= Proce note where, such drive with it (an expense)					
3. Spot 50sx plug fr/3850-3200(7"shoe,Queen) Tag @ 3138					
4. Spot 25sx plug fr/1300-1050(T-salt, 9 5/8 shoe) Tag @ 1018 5. Circ cmt fr/200 to surf w/30sx (13" shoe-surf) Tag @ surf					
6. Install dry hole marker 10-28-02					
Approved as to plugging of the Well Bore.					
Liability under the rains retained until				•	
surface restoration is completed.				(*,)	
I homely a self-ul and all				<i></i>	
I hereby certify that the inform	atten above is true and comp	lete to the best of my knowled	lge and belief.		
SIGNATURE	21		/	- 1-1-1	
T // U		THEE THINGS	200321	DATE 10/28/02	
Type or print name (This space for State use).	my BAGLEY		Telep	hone No.915 520-8754	
Space for State use),	1			11. 10.00	
APPPROVEDBY	**	_TITLE		FEB 0 1 2003	
Conditions of approval, if any: OC FIELD REPRESENTA	TIVE ILISTAFE MANAGER	+ 1 1/11		DATE	
7. 1. 1	HIVE HYSTALL HONGO COM				
GWW					