NE' MEXICO OIL CONSERVATION C' MISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or its agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

NOTICE OF INTENTION TO TEST CASING SHUT-OFF	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL
NOTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO PULL OR
	OTHERWISE ALTER CASING
SOTICE OF INTENTION TO REPAIR WELL	NOTICE OF INTENTION TO PLUG WELL
NOTICE OF INTENTION TO DEEPEN WELL	
**	W. W. J. 1008
nove,	New Mexico February 3 _{Nate} 1937
IL CONSERVATION COMMISSION, anta Fe, New Mexico.	
entlemen:	
collowing is a notice of intentiton to do certain work as	described below at the
	Well No gov in cri
tanglind Old pend Gas Company Capps	
Sec	, N. M. P. M., Hobbs Field
Lea County County.	
FULL DETAILS OF P	ROPOSED PLAN OF WORK
FOLLOW INSTRUCTIONS IN THE RUL	ES AND REGULATIONS OF THE COMMISSION
At 11 AM February 5, 193	7 72 hours will have elapsed
at which time we plan to test 3 5/8	3* OD new casing for shut off
at which time we plan to test 9 5/8 in the following manner: build up	3* OD new casing for shut off
at which time we plan to test 9 5/8 in the following manner: build up and allow to stand for 30 minutes.	3° OD new casing for shut off 1200# on casing close valves
at which time we plan to test 3 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8" OD 40% SS new casi	3* OD new casing for shut off 1200# on casing close valves ing set at 1670' and comented
at which time we plan to test 9 5/8 in the following manner: build up and allow to stand for 30 minutes.	3* OD new casing for shut off 1200# on casing close valves ing set at 1670' and comented
at which time we plan to test 3 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8" OD 40% SS new casi	3* OD new casing for shut off 1200# on casing close valves ing set at 1670' and comented
at which time we plan to test 9 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8" OD 40% SS new casi	3* OD new casing for shut off 1200# on casing close valves ing set at 1670' and comented
at which time we plan to test 9 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8" OD 40# SS new casi	3* OD new casing for shut off 1200# on casing close valves ing set at 1670' and comented
at which time we plan to test 9 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8" OD 40# SS new casi	3* OD new casing for shut off 1200# on casing close valves ing set at 1670' and cemented
at which time we plan to test 3 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8" OD 40# SS new casi	3* OD new casing for shut off 1200# on casing close valves ing set at 1670' and comented
at which time we plan to test 9 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8 0D 40 88 new casi with 575 sax, February 2, 1937, 11	3* OD new casing for shut off 1200# on casing close valves ing set at 1670' and cemented
at which time we plan to test 9 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8 OD 40 SS new casi with 575 sax, February 2, 1937, 11	3* OD new casing for shut off 1200# on casing close valves ing set at 1670* and cemented AM.
at which time we plan to test 9 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8 OD 40 SS new casi with 575 sax, February 2, 1937, 11	3* OD new casing for shut off 1200# on casing close valves ing set at 1670' and comented
at which time we plan to test 9 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8 OD 40 SS new casi with 575 sax, February 2, 1937, 11	3* OD new casing for shut off 1200# on casing close valves ing set at 1670* and cemented AM.
at which time we plan to test 9 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8 OD 40 SS new casi with 575 sax, February 2, 1937, 11	Stemolind (il and Ges Compensed By Alexander Company or Operator B
at which time we plan to test 9 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8 OD 40 SS new casi with 575 sax, February 2, 1937, 11	Stanolind Wil and Ges Company or Operator By XIGHARLANGE COMPANY OF OPERATOR
at which time we plan to test 9 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8 0D 40 SS new casi with 575 sax, February 2, 1937, 11 Approved	Stanolind Oil and Ges Company By X Company or Operator Position Field Supt. Send communications regarding well to
at which time we plan to test 3 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8" OD 40% SS new casi with 575 sax, February 2, 1937, 11	Stemolind (il and Ges Compense) By Company or Operator Position Field Supt. Send communications regarding well to
at which time we plan to test 3 5/8 in the following manner: build up and allow to stand for 30 minutes. 9 5/8 0D 40 SS new casi with 575 sax, February 2, 1937, 11 Approved 2 secept as follows:	Stanolind Oil and Ges Company By X Company or Operator Position Field Supt. Send communications regarding well to

and the state of t

Superposition of the second

and the second of the second o

er ar i i wezh Nordan A

Like of the Angles

and the second second

the second of th

type in the second ing that en agreem

•

en general gen