STATE OF NEW MEXICO ENERGY AND ASSERBLES DEPARTMENT

THE THIRD IS NOT THE PARTY OF T	CHYH	INIE
HO. OF COPIES SECCIVED	1	
DISTRIBUTION	1	
SANTA FX	7	
1162		
U.1.G.1.	1	
LAND OFFICE		
02534703		

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 -

.... OU1 22 1982

SANTA FE, NEW MEXICO 87501 U.S.G.S. LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS TOO HOT USE THIS FORM FOR PROPOSALS TO OBTILL OR TO BETTEN GO PLUS DACK TO A DIFFERENT RESERVOIR.	State X Fee State Oil & Gas Leana No. A-1212
SUNDRY NOTICES AND REPORTS ON WELLS TOO HOT USE THIS FORM FOR PROPERTY TO BELL ON TO BE	State X Fee 5, State Off & Gas Leana No.
SUNDRY NOTICES AND REPORTS ON WELLS 100 HOT USE THIS FORM FOR PROPOSALS TO DELICE ON TO BELL ON TO	
TO THE CALL THE PROPOSALE I	A-1212
TO THE CALL THE PROPOSALE I	THITTIES IN STREET
TO THE CALL THE PROPOSALE I	
1.	
well sas other. Injection	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Nume
Amoco Production Company	South Hobbs (GSA) Uni
1. Address of Operator	91 No.
P. O. Box 68, Hobbs, NM 88240	31
	10. Field and Pool, or bridget
UNIT LETTER E 2310 FEET FROM THE NORTH LINE AND 990 FEET FROM	Hobbs GSA
THE West LINE, SECTION 4 TOWNSHIP 19-S RANGE 38-E NAPH.	
15. Elevation (Show whether DF, RT, GR, etc.)	
3611' GL	12. County
	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	her Data
SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK X	
TEMPORARILY ABANDON COMMENCE DRILLING OPHS	ALTERING CASING
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	PEUG AND ABANGONMENT
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	
Moved in service unit 10-11-82. Pulled tubing and packer. Dumper Tagged sand at 4045' and cleaned out to 4100'. Capped sand with Set a cement retainer at 3897'. Squeezed with 100 sacks class C C with 5# Tuff Plug/sack. Reversed out 32 sacks. Tagged up at 3 cement retainer and cement to 3949'. Pressure tested casing to 1 Drilled out cement to 4095'. Pressure tested squeeze to 1500 psi 400 psi in 40 min. Drilled out Cal Seal and sand to 4250' and ci Ran packer, seating nipple, and 2-3/8" tubing. Set packer at 386 blowout preventer. Moved out service unit 10-16-82. Returned we 0+4-NMOCD, H 1-HOU 1-SUSP 1-CLF	5 ft. of Cal Seal. and 35 sacks class 8896'. Drilled out 500 psi and OK. and bled down to rc. hole clean.
5. I hereby certify that the information above is true and complete to the best of my knowledge and belief. ICHED CATRY T. Forman TITLE ASST. Admin. Analyst	DATE 10-20-82

OL & GAS INSPECTOR