




COUNTY Lea

STATE _____

OPERATOR Standard

FARM S.E. Wm Jerry

WELL NO. 8

Sec. 9

T. 19

R. 38

AREA _____

N. 1980

E. 1980

S. _____

W. _____

Sec. _____

Blk. _____

Survey _____

SPUD 6/21/37

COMP. 8/2/37

T. D. _____

ELEV. _____

CONTRACTOR _____

TOOLS _____

SHOT 7128

ACID 4000 Gal.

Gal. _____

ACID _____

Gal. _____

Formations

T. An. _____
T. S. _____
B. S. _____
T. Br. L. _____
R. Sd. _____
T. Wh. L. _____
T. Del. L. _____
T. Del. Sd. 4128

PRODUCTION

OPEN _____ bbl. OIL _____ cu. ft. GAS _____
TUBING _____ bbl. OIL _____ cu. ft. GAS _____
RETEST _____
PRESSURE: CASING _____ TUBING _____
REMARKS: _____

CASING:

Size	Depth	Cement
<u>12 1/2"</u>	<u>196</u>	<u>275</u>
<u>9 1/2"</u>	<u>1615</u>	<u>300</u>
<u>7"</u>	<u>4058</u>	<u>300</u>
TUBING		
<u>8"</u>	<u>4186</u>	
<u>2 1/2"</u>		

		<u>7-27</u>	<u>Packer 4163</u>
<u>6-1</u>	<u>M in M</u>		<u>acidizing with</u>
<u>6-8</u>	<u>TD 215' rt on 200</u>		<u>2000 gal</u>
<u>6-15</u>	<u>TD 1620' 200</u>		<u>Seabbing out</u>
<u>6-22</u>	<u>Ø 3060 A-L</u>	<u>TD 4186 L</u>	<u>this morning</u>
<u>6-29</u>	<u>Ø 3852 L</u>		
<u>7-6</u>	<u>TD 4066 L</u>		<u>40 bbl per hr</u>
	<u>drill pipe stuck</u>		<u>5 hrs.</u>
<u>7-13</u>	<u>TD 4163 L</u>		<u>prop to test</u>
<u>7-20</u>	<u>TD 4163 L</u>		<u>putting tubing</u>
	<u>to drill better pay</u>	<u>8-3</u>	<u>TD 4186 L</u>
	<u>4000</u>		<u>I P flowed</u>
			<u>9372 bbls</u>
			<u>24 hrs + 198 water</u>
			<u>then open tubing</u>
			<u>7,827,600 gal</u>

LOG

42 cal
215 rr rbshe

1650

75 A

2010 X

40 KR N

2220 X

64 A P

2440 A P

54 A

3030 A